

FORM 6 Rev 12/05	State of Colorado Oil and Gas Conservation Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109		DE ET OE ES
			Date Received: 05/10/2011 Document Number: 1635718

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: <u>28600</u>	Contact Name: <u>MARK CORNETT</u>
Name of Operator: <u>EXXON MOBIL CORPORATION</u>	Phone: <u>(281) 654-1925</u>
Address: <u>P O BOX 4358</u>	Fax: <u>(281) 654-1940</u>
City: <u>HOUSTON</u> State: <u>TX</u> Zip: <u>77210-43</u>	Email: <u>MARK.CORNETT@EXXONMOBIL.COM</u>
For "Intent" 24 hour notice required, COGCC contact:	Name: <u>LONGWORTH, MIKE</u> Tel: <u>(970) 812-7644</u> Email: <u>mike.longworth@state.co.us</u>

API Number: <u>05-103-10060-00</u>	Well Name: <u>PICEANCE CREEK</u>	Well Number: <u>4604</u>
Location: QtrQtr: <u>NWSW</u> Section: <u>8</u> Township: <u>2S</u> Range: <u>97W</u> Meridian: <u>6</u>	County: <u>RIO BLANCO</u> Federal, Indian or State Lease Number: <u>COC57286</u>	
Field Name: <u>LOVE RANCH</u>	Field Number: <u>51850</u>	

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.889710 Longitude: -108.311380

GPS Data:
 Date of Measurement: 04/03/2008 PDOP Reading: 2.3 GPS Instrument Operator's Name: L. Scott

Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems

Other _____

Casing to be pulled: Yes No Top of Casing Cement: _____

Fish in Hole: Yes No If yes, explain details below

Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below

Details: **WELL WAS DRILLED IN OCTOBER 2001. IT HAS CEMENTED SURFACE CASING SET AT 400', BUT DUE TO DRILLING PROBLEMS, THE WELL WAS ABANDONED AND NO FURTHER DRILLING WAS ATTEMPTED. THERE IS NO FUTURE UTILITY FOR THE WELLBORE.**

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
Total: 0 zone(s)					

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	17+1/2	13+3/8	54.5	401	365	401	0	

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIPB #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIPB #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 310 sks cmt from 0 ft. to 401 ft. in Plug Type: CASING Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. in Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. in Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. in Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. in Plug Type: _____ Plug Tagged:

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:
Set _____ sacks at surface
Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____
*Wireline Contractor: _____ *Cementing Contractor: _____
Type of Cement and Additives Used: _____
Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: MARK CORNETT
Title: SR REGULATORY SPECIALIST Date: 5/6/2011 Email: NARK.CORNETT@EXXONMOBIL.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: KING, KEVIN Date: 5/13/2011

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: 11/12/2011

IMPORTANT: SOME DATA FIELDS HAVE BEEN MODIFIED.

Attachment Check List

Att Doc Num	Name
1635718	FORM 6 INTENT SUBMITTED
1635719	WELLBORE DIAGRAM
1635720	OPERATIONS SUMMARY

Total Attach: 3 Files

General Comments

User Group	Comment	Comment Date

Total: 0 comment(s)