



**CEMENTER'S WELL SERVICE, INC.**  
 P.O. BOX 338220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7712

OUR INVOICE

**198725**

Rig 32

(P.O.# 94407)

Date 12/20/2010	Well Owner P.D.C	Well No. 10-04	Lease BINDER
County WELD	State COLORADO	Field	
Charge to EASTON U.S. DRILLING	Charge Code		For Office Use Only
Address P.O. BOX 17805 (EASTON # 32)			
City, State DENVER, COLORADO 80217			
Pump Truck No. 1201	Code	Bulk Truck No. 1217	Code
Type of Job	Depth	Fl. 434	To
Surface 8 5/8" CSG 24"	Bottom of Surface	Fl. 430	To
Plug	Plug Landed @ 409	Fl. Time On 0200	
Production	Pipe Landed @ 430	Fl. Plug Down 0415	

Reference No.	Description	Qty.	Meas.	Unit P
	Pump Truck Charge			
	Cement Neat ✓	310	SKS	
	Poz. Mix			
	Calcium Chloride	3.9%		
	Gel % Flo-Cole 1/4 #Per Sack			
	Handling Charge			
	Hauling Charge			
	Additional Cement			
	MIXING RATE 4 BPM			
	DISP RATE 5 BPM			
	SLURRY VOL 1.18 CU FT/SK			
	SLURRY WT 14.8-15.0 PPG			
	WATER TEMP 43			
	PLUG LANDED @ 200 PSI			
	TOTAL SLURRY VOL 65 BALS CEMENT			

PRE-FLUSH W/15 BBLS H <sub>2</sub> O	Tax Reference Code	Sub Total
DISPLACE W/26 BBLS H <sub>2</sub> O	State CO 2.9 %	Tax
CIRCULATE 4 BBLS CEMENT	Disc.	Total

Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming
1201		Pump Truck		38	
1217		Bulk Truck		38	

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to change.

Delivered By JIM/OSCAR/STEVE

Received By Jim New  
 Customer or His Agent