

FORM

6

Rev
12/05

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Date Received:

Document Number:

400164429

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 100185 Contact Name: RUTHANN MORSS
 Name of Operator: ENCANA OIL & GAS (USA) INC Phone: (720) 876-5060
 Address: 370 17TH ST STE 1700 Fax: (720) 876-6060
 City: DENVER State: CO Zip: 80202-56 Email: RUTHANN.MORSS@ENCANA.COM

24 hour notice required, contact: Name: LONGWORTH, MIKE Tel: (970) 812-7644
 Email: mike.longworth@state.co.us

API Number 05-045-10263-00
 Well Name: BOULTON Well Number: 33-10A(G33NE)
 Location: QtrQtr: SWNE Section: 33 Township: 6S Range: 92W Meridian: 6
 County: GARFIELD Federal, Indian or State Lease Number: _____
 Field Name: MAMM CREEK Field Number: 52500

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.484342 Longitude: -107.667286
 GPS Data:
 Data of Measurement: 05/06/2010 PDOP Reading: 2.6 GPS Instrument Operator's Name: BBirdsall
 Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems
 Other _____
 Casing to be pulled: Yes No Top of Casing Cement: _____
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Code	Perf. Top	Perf. Bottom	Date	Method of Isolation	Plug Depth

Total: 0 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	9+40/64	32.3	409	175	411	0	
1ST	8+1/2	5+1/2	15.5	1,267	350	1,267	28	

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 600 with 7 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 20 sks cmt from 480 ft. to 330 ft. in Plug Type: CASING Plug Tagged:
Set 10 sks cmt from 65 ft. to 0 ft. in Plug Type: CASING Plug Tagged:
Set 5 sks cmt from 15 ft. to 0 ft. in Plug Type: ANNULUS Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. in Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. in Plug Type: _____ Plug Tagged:
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)
Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:
Set _____ sacks at surface
Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: 04/28/2011
*Wireline Contractor: MESA WIRELINE *Cementing Contractor: SCHLUMBERGER
Type of Cement and Additives Used: CLASS G NEAT
Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Provide Technical Detail:

1. UNLAND TBG. TOOH.
2. RU MESA WIRELINE. RIH WITH 4/5" GAUGE RING
3. SET CIBP @ 600'. PRESSURE TEST CSG TO 500 PSI 15 MIN. GOOD
4. MIX AND PUMP 7 SX 15.8 PPG G NEAT. DISPLACE 2 BBLs WATER.
5. TOOH TO 480'. MIX AND PUMP 20 SX 15.8 PPG G NEAT. DISPLACE 1 BBL WATER
6. TAG TOC@330'
7. DIG OUT AND CUT OFF CASING 4' BELOW GROUND.
8. RIH WITH 1" PIPE TO 65'
9. PUMP AND MIX 10 SX CLASS G TO SURFACE INSIDE 5.5" CASING AND 5 SX CLASS G IN ANNULUS 15'- SURFACE.
10. WELD ON MARKER PLATE AND BACK FILL HOLE.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: RUTHANN MORSS
Title: REGULATORY ANALYST Date: _____ Email: RUTHANN.MORSS@ENCANA.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY:

Attachment Check List

Att Doc Num	Name
400164473	WIRELINE JOB SUMMARY
400164474	CEMENT JOB SUMMARY
400164476	WELLBORE DIAGRAM
400166995	CEMENT JOB SUMMARY

Total Attach: 4 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total: 0 comment(s)