

FORM  
6Rev  
12/05State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Date Received:

Document Number:

400171410

## WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 10267

Contact Name: Mathew Goolsby

Name of Operator: VECTA OIL &amp; GAS LTD

Phone: (303) 618-7736

Address: 575 UNION BLVD #208

Fax: (303) 945-2869

City: LAKEWOOD State: CO Zip: 80228

Email: matgoolsby@vecta-denver.com

24 hour notice required, contact:

Name:

Tel:

Email:

API Number 05-017-07699-00

Well Name: TORREYS

Well Number: 44-33

Location: QtrQtr: SESE Section: 33 Township: 13S Range: 47W Meridian: 6

County: CHEYENNE

Federal, Indian or State Lease Number:

Field Name: WILDCAT

Field Number: 99999

☐ Notice of Intent to Abandon☒ Subsequent Report of Abandonment

## Only Complete the Following Background Information for Intent to Abandon

Latitude: 38.868510

Longitude: -102.669320

GPS Data:

Data of Measurement: 01/12/2011

PDOP Reading: 1.7

GPS Instrument Operator's Name: Sally Pettibone

Reason for Abandonment: ☐ Dry ☐ Production for Sub-economic ☐ Mechanical Problems☐ OtherCasing to be pulled: ☐ Yes ☐ No

Top of Casing Cement:

Fish in Hole: ☐ Yes ☐ No

If yes, explain details below

Wellbore has Uncemented Casing leaks: ☐ Yes ☐ No

If yes, explain details below

Details:

## Current and Previously Abandoned Zones

Formation Code Perf. Top Perf. Bottom Date Method of Isolation Plug Depth

--	--	--	--	--	--	--

Total: 0 zone(s)

## Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	418	250	418	0	VISU

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIPB #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIPB #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set	80	sks cmt from	5090	ft. to	5270	ft. in	Plug Type:	OPEN HOLE	Plug Tagged:	<input type="checkbox"/>
Set	40	sks cmt from	4596	ft. to	4776	ft. in	Plug Type:	OPEN HOLE	Plug Tagged:	<input type="checkbox"/>
Set	40	sks cmt from	2270	ft. to	2450	ft. in	Plug Type:	OPEN HOLE	Plug Tagged:	<input type="checkbox"/>
Set	40	sks cmt from	1870	ft. to	2050	ft. in	Plug Type:	OPEN HOLE	Plug Tagged:	<input type="checkbox"/>
Set	40	sks cmt from	1520	ft. to	1700	ft. in	Plug Type:	OPEN HOLE	Plug Tagged:	<input type="checkbox"/>

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 50 sacks half in. half out surface casing from 230 ft. to 450 ft. Plug Tagged: ☐

Set 10 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☒ No

Set 10 sacks in rat hole Set 10 sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: 0 ft. of \_\_\_\_\_ inch casing

Plugging Date: 01/09/2011

\*Wireline Contractor: \_\_\_\_\_

\*Cementing Contractor: Allied Cementing (Oakley, KA)

Type of Cement and Additives Used: Class A common

Flowline/Pipeline has been abandoned per Rule 1103 ☐ Yes ☐ No

\*ATTACH JOB SUMMARY

Provide Technical Detail:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_

Print Name: Mathew Goolsby

Title: VP Operations

Date: \_\_\_\_\_

Email: matgoolsby@vecta-denver.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: \_\_\_\_\_

Date: \_\_\_\_\_

### CONDITIONS OF APPROVAL, IF ANY:

### Attachment Check List

Att Doc Num	Name
400171411	WELLBORE DIAGRAM
400171412	CEMENT JOB SUMMARY

Total Attach: 2 Files

**General Comments**

<b><u>User Group</u></b>	<b><u>Comment</u></b>	<b><u>Comment Date</u></b>

Total: 0 comment(s)