

FORM
6
Rev
12/05

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Date Received:
06/07/2011

Document Number:
1636681

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.
A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 8667 Contact Name: TOM MELLAND
Name of Operator: PETROGLYPH ENERGY INC Phone: (719) 742-5570
Address: 555 S COLE RD Fax: (719) 742-5571
City: BOISE State: ID Zip: 83707 Email: TMELLAND@PGEI.COM

For "Intent" 24 hour notice required, COGCC contact: Name: DURAN, JOHN Tel: (719) 846-4715
Email: john.duran@state.co.us

API Number 05-055-06265-00
Well Name: ANSELMO Well Number: 07-12
Location: QtrQtr: NWSW Section: 7 Township: 29S Range: 66W Meridian: 6
County: HUERFANO Federal, Indian or State Lease Number: _____
Field Name: PURGATOIRE RIVER Field Number: 70830

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 37.535267 Longitude: -104.830584
GPS Data:
Data of Measurement: 08/10/2010 PDOP Reading: 6.0 GPS Instrument Operator's Name: GARY L. TERRY
Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems
 Other _____
Casing to be pulled: Yes No Top of Casing Cement: 600
Fish in Hole: Yes No If yes, explain details below
Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
VERMEJO COAL	1326	1527			

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	11	8+5/8	23	973	261	973	0	
1ST	7+7/8	5+1/2	15.5	1,666	110	1,666	600	

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 1301 with 84 sacks cmt on top. CIPB #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIPB #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 135 sks cmt from 489 ft. to 4 ft. in Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. in Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. in Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. in Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. in Plug Type: _____ Plug Tagged:

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

PETROGLYPH OPERATIN, RATON BASIN WELLS
GENERAL PLUGGING PROCEDURE:

*A RIG WILL PULL AND LD RODS AND TUBING IN ALL WELLS BEFORE PLUGGING CONTRACTOR ARRIVES.

*A WIRELINE COMANAY WILL SET CIBPS APPROX. 25 FT. ABOVE TOP PERFORATION IN ALL WELLS BEFOR PLUGGING CONTRACTOR ARRIVES.

*MIRU PLUGGING CONTRACTOR.

*RIH WITH TUBING, TAG CIBP AND CEMENT BOTTOM TO TOC (TOP OF PRODUCTION CEMENT). POOH WITH TUBING.

*MIRU WIRLINE CONTRACTOR, GIH AND CUT PRODUCTION CASING AT 3RD PRODUCTION CASING COUPLING ABOVE TOC.

*POOH AN LD CASING.

*RIH WITH TUBING TO TOP OF CASING CUT AND CEMENT BOTTOM TO TOP (4' BELOW GROUND LEVEL).

*DIG CELLAR AROUND SURFACE CASING AND CUT CASING 4 FT BELOW GL AND WELD PLATE ON TOP.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: TOM MELLAND

Title: DISTRICT MANAGER Date: 6/3/2011 Email: TMELLAND@PGEI.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: SUTPHIN, DIRK

Date: 6/16/2011

CONDITIONS OF APPROVAL, IF ANY:

Expiration Date: 12/15/2011

1) Provide 48 hour notice of MIRU to John Duran at 719-846-4715 or email John.Duran@state.co.us.

Attachment Check List

Att Doc Num	Name
1636681	FORM 6 INTENT SUBMITTED
1636682	WELLBORE DIAGRAM

Total Attach: 2 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Engineer	Form as submitted was NO to pulling casing but based on TOC, proposed plug #2 volume and procedure it should be YES.	6/16/2011 4:47:44 PM

Total: 1 comment(s)