


FORM 6 Rev 12/05	State of Colorado Oil and Gas Conservation Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109		<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:25%;">DE</td> <td style="width:25%;">ET</td> <td style="width:25%;">OE</td> <td style="width:25%;">ES</td> </tr> </table> Date Received: 07/18/2011 Document Number: 2568239	DE	ET	OE	ES																
DE	ET	OE	ES																				
WELL ABANDONMENT REPORT																							
<p>This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.</p> <p>A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.</p>																							
OGCC Operator Number: <u>10228</u>		Contact Name: <u>PAUL MENDELL</u>																					
Name of Operator: <u>NATURAL GAS CORPORATION OF AMERICA</u>		Phone: <u>(303) 663-2902</u>																					
Address: <u>401 OROFINO DR</u>		Fax: _____																					
City: <u>CASTLE ROCK</u>	State: <u>CO</u>	Zip: <u>80108</u>	Email: <u>PAULMENDELL@COMCAST.NET</u>																				
<table style="width:100%;"> <tr> <td style="width:30%;"> For "Intent" 24 hour notice required, COGCC contact: </td> <td style="width:35%;"> Name: <u>QUINT, CRAIG</u> </td> <td style="width:35%;"> Tel: <u>(719) 767-8939</u> </td> </tr> <tr> <td></td> <td colspan="2"> Email: <u>craig.quint@state.co.us</u> </td> </tr> </table>				For "Intent" 24 hour notice required, COGCC contact:	Name: <u>QUINT, CRAIG</u>	Tel: <u>(719) 767-8939</u>		Email: <u>craig.quint@state.co.us</u>															
For "Intent" 24 hour notice required, COGCC contact:	Name: <u>QUINT, CRAIG</u>	Tel: <u>(719) 767-8939</u>																					
	Email: <u>craig.quint@state.co.us</u>																						
<table style="width:100%;"> <tr> <td style="width:20%;">API Number</td> <td colspan="3"><u>05-017-07661-00</u></td> </tr> <tr> <td>Well Name:</td> <td><u>HAMMER</u></td> <td>Well Number:</td> <td><u>6-5</u></td> </tr> <tr> <td>Location:</td> <td>QtrQtr: <u>SWNW</u></td> <td>Section: <u>6</u></td> <td>Township: <u>15S</u> Range: <u>50W</u> Meridian: <u>6</u></td> </tr> <tr> <td>County:</td> <td colspan="3"><u>CHEYENNE</u></td> </tr> <tr> <td>Field Name:</td> <td><u>WILDCAT</u></td> <td>Field Number:</td> <td><u>99999</u></td> </tr> </table>				API Number	<u>05-017-07661-00</u>			Well Name:	<u>HAMMER</u>	Well Number:	<u>6-5</u>	Location:	QtrQtr: <u>SWNW</u>	Section: <u>6</u>	Township: <u>15S</u> Range: <u>50W</u> Meridian: <u>6</u>	County:	<u>CHEYENNE</u>			Field Name:	<u>WILDCAT</u>	Field Number:	<u>99999</u>
API Number	<u>05-017-07661-00</u>																						
Well Name:	<u>HAMMER</u>	Well Number:	<u>6-5</u>																				
Location:	QtrQtr: <u>SWNW</u>	Section: <u>6</u>	Township: <u>15S</u> Range: <u>50W</u> Meridian: <u>6</u>																				
County:	<u>CHEYENNE</u>																						
Field Name:	<u>WILDCAT</u>	Field Number:	<u>99999</u>																				
<input checked="" type="checkbox"/> Notice of Intent to Abandon <input type="checkbox"/> Subsequent Report of Abandonment																							
<i>Only Complete the Following Background Information for Intent to Abandon</i>																							
Latitude: <u>38.772410</u>		Longitude: <u>-103.050690</u>																					
GPS Data:																							
Data of Measurement: _____		PDOP Reading: _____ GPS Instrument Operator's Name: _____																					
Reason for Abandonment: <input type="checkbox"/> Dry <input checked="" type="checkbox"/> Production for Sub-economic <input type="checkbox"/> Mechanical Problems																							
<input type="checkbox"/> Other _____																							
Casing to be pulled: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Top of Casing Cement: _____																					
Fish in Hole: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		If yes, explain details below																					
Wellbore has Uncemented Casing leaks: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		If yes, explain details below																					
Details: _____																							
Current and Previously Abandoned Zones																							
<u>Formation</u>	<u>Perf. Top</u>	<u>Perf. Btm</u>	<u>Abandoned Date</u>	<u>Method of Isolation</u>	<u>Plug Depth</u>																		
NIOBRARA	702																						
Total: 1 zone(s)																							
Casing History																							
Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status															
SURF	6+1/4	4+1/2	9.5	465	46	465	0																
OPEN HOLE	3+1/2			825																			

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIPB #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIPB #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set _____	sks cmt from _____	ft. to _____	ft. in _____	Plug Type: _____	Plug Tagged: <input type="checkbox"/>
Set _____	sks cmt from _____	ft. to _____	ft. in _____	Plug Type: _____	Plug Tagged: <input type="checkbox"/>
Set _____	sks cmt from _____	ft. to _____	ft. in _____	Plug Type: _____	Plug Tagged: <input type="checkbox"/>
Set _____	sks cmt from _____	ft. to _____	ft. in _____	Plug Type: _____	Plug Tagged: <input type="checkbox"/>
Set _____	sks cmt from _____	ft. to _____	ft. in _____	Plug Type: _____	Plug Tagged: <input type="checkbox"/>

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 10 sacks half in. half out surface casing from 520 ft. to 370 ft. Plug Tagged: ☒

Set 10 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☒ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1103 ☐ Yes ☐ No *ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: ARON RASON

Title: SALES ASSISTANT Date: 7/15/2011 Email: ARONRT@HOTMAIL.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: BURN, DIANA Date: 7/20/2011

CONDITIONS OF APPROVAL, IF ANY: _____

Expiration Date: 1/19/2012

IMPORTANT: SOME DATA FIELDS HAVE BEEN MODIFIED.

- 1) Provide 24 hour notice of MIRU to Craig Quint at 719-342-5702 or e-mail Craig.Quint@state.CO.US.
- 2) For 520' plug: pump plug and displace, shut-in, WOC 4 hours and tag plug. Leave at least 100' cement in the casing for each plug.
- 3) Operator must provide well location GPS coordinates on Subsequent Report of Abandonment in accordance with COGCC As-Built Location Policy and Rule 215.
- 4) If unable to plug as prescribed, contact COGCC for changes in plugging orders.
- 5) Monthly Report of Operations, Form 7 required from spud to abandonemnt - submit these reports to COGCC prior to Subsequent Report of Abandonment.
- 6) Confirm open hole dimension on Subsequent Report of Abandonment.

Attachment Check List

Att Doc Num	Name
2568239	FORM 6 INTENT SUBMITTED
2568240	WELLBORE DIAGRAM

Total Attach: 2 Files

General Comments

User Group	Comment	Comment Date

Total: 0 comment(s)