



400193993

5

<b>FORM</b> 6 Rev 02/11	<b>State of Colorado</b> <b>Oil and Gas Conservation Commission</b> 1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109		<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:25%;">DE</td> <td style="width:25%;">ET</td> <td style="width:25%;">O</td> <td style="width:25%;">ES</td> </tr> <tr> <td colspan="4" style="text-align: center; font-weight: bold;">RECEIVED</td> </tr> <tr> <td colspan="4">Date Received: <b>AUG 09 2011</b></td> </tr> <tr> <td colspan="4">COGCC/Rifle Office Document Number:</td> </tr> </table>	DE	ET	O	ES	RECEIVED				Date Received: <b>AUG 09 2011</b>				COGCC/Rifle Office Document Number:			
DE	ET	O	ES																
RECEIVED																			
Date Received: <b>AUG 09 2011</b>																			
COGCC/Rifle Office Document Number:																			
<b>WELL ABANDONMENT REPORT</b>																			
<p><small>This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.</small></p> <p><small>A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.</small></p>																			
OGCC Operator Number: <u>74740</u>		Contact Name: <u>Mike Hayes</u>																	
Name of Operator: <u>Rio Mesa Resources Inc.</u>		Phone: <u>(970) 620-2257</u>																	
Address: <u>226 1/2 E. Main</u>		Fax: <u>(970) 675-5137</u>																	
City: <u>Rangely</u>	State: <u>Co.</u>	Zip: <u>81648</u>	Email: <u>hayespetro@centurytel.net</u>																
For intent 24 hour notice required, Name: _____		Tel: _____																	
COGCC contact: _____		Email: _____																	
API Number <u>05-103-40024-</u> <u>COCC # 10340285</u>																			
Well Name: <u>Government Petrel</u>		Well Number: <u>#3</u>																	
Location: <u>QtrQtr: SE NE</u>	Section: <u>11</u>	Township: <u>1N</u>	Range: <u>R102</u>																
Meridian: <u>6 pm</u>		County: <u>Rio Blanco, Co.</u>																	
Federal, Indian or State Lease Number: <u>COC57552</u>		Field Name: <u>Rangely Mancos</u>																	
Field Number: _____																			
<input type="checkbox"/> Notice of Intent to Abandon																			
<input checked="" type="checkbox"/> Subsequent Report of Abandonment																			
<i>Only Complete the Following Background Information for Intent to Abandon</i>																			
Latitude: <u>40.07107N</u>		Longitude: <u>108.80426W</u>																	
GPS Data: <u>7/13/2011</u>																			
Date of Measurement: <u>NA</u>		PDOP Reading: <u>NA</u>																	
GPS Instrument Operator's Name: <u>Erika Miller (Blm)</u>																			
Reason for Abandonment: <input type="checkbox"/> Dry <input checked="" type="checkbox"/> Production for Sub-economic <input type="checkbox"/> Mechanical Problems																			
<input type="checkbox"/> Other _____																			
Casing to be pulled: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Top of Casing Cement: <u>None</u>																	
Fish in Hole: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		If yes, explain details below																	
Wellbore has Uncemented Casing leaks: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		If yes, explain details below																	
Details: <u>no cement on surface casing</u>																			
<b>Current and Previously Abandoned Zones</b>																			
Formation	Code	Perf. Top	Perf. Btm																
Date	Method of Isolation	Plug Depth																	
Mancos			Open hole																
Total: 0 zone(s)																			
<b>Casing History</b>																			
Casing Type	Size of Hole	Size of Casing	Weight Per Foot																
Setting Depth	Sacks Cement	Cement Bot	Cement Top																
Status																			
		6"																	



### Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIPB #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
 CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIPB #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
 CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set _____	sks cmt from _____	ft. to _____	ft. in _____	Plug Type: _____	Plug Tagged: <input type="checkbox"/>
Set _____	sks cmt from _____	ft. to _____	ft. in _____	Plug Type: _____	Plug Tagged: <input type="checkbox"/>
Set _____	sks cmt from _____	ft. to _____	ft. in _____	Plug Type: _____	Plug Tagged: <input type="checkbox"/>
Set _____	sks cmt from _____	ft. to _____	ft. in _____	Plug Type: _____	Plug Tagged: <input type="checkbox"/>
Set _____	sks cmt from _____	ft. to _____	ft. in _____	Plug Type: _____	Plug Tagged: <input type="checkbox"/>

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
 Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
 Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
 (Cast Iron Cement Retainer Depth)

Set \_\_\_\_\_ sacks half in. half out surface casing from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Tagged: ☐

Set 13 sacks at surface

Cut four feet below ground level, weld on plate

Above Ground Dry-Hole Marker: ☐ Yes

☒ No

Set \_\_\_\_\_ sacks in rat hole

Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ inch casing Plugging Date: \_\_\_\_\_

\*Wireline Contractor: \_\_\_\_\_

\*Cementing Contractor: \_\_\_\_\_

Type of Cement and Additives Used: Portland sack

Flowline/Pipeline has been abandoned per Rule 1103 ☒ Yes ☐ No

\*ATTACH JOB SUMMARY

Provide Technical Detail:

Back fill hole with shale & sand to 50' from surface & set 50' cement plug, cut off casing 4' below surface and weld on plate with info.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: Mike Hayes

Print Name: Mike Hayes

Title: Owner

Date: 08/04/2011

Email: hayespetro@centurytel.net

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: [Signature]

Date: 8/10/11

CONDITIONS OF APPROVAL, IF ANY:



### Attachment Check List

Att Doc Num	Name

Total Attach: \_\_\_\_\_

P7=BLANK

← 303



Sales Receipt  
HERITAGE BUILDING & HOME CENTER INC.  
226 F MAIN  
RANGELY, COLORADO 81648

\*\* Copy \*\*

Receipt #: D3138 11:44 AM 7/22/11  
Invoice No: G31080  
Customer : 8765  
Cust P O: Petrel Gov. #3  
Salesperson: john

Rio Mesa Resources  
226-1/2 E. Main  
Rangely CO 81648

Qty	Description	Price
13	Portland Cement	
	94Lb.	161.33
Retail:13.79; Savings:17.94		

Total Savings: \$17.94

Subtotal	161.33
Totl Tax	10.49
TOTAL	171.82

Amount Tendered: \$171.82 Charged On Acct

Signature

A handwritten signature in black ink, appearing to read "Mike Hume".

WE APPRECIATE YOUR BUSINESS.  
PLEASE COME BACK SOON!

