

FORM
6

Rev
12/05

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Date Received:

Document Number:

400205488

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 100185 Contact Name: RUTHANN MORSS
Name of Operator: ENCANA OIL & GAS (USA) INC Phone: (720) 876-5060
Address: 370 17TH ST STE 1700 Fax: (720) 876-6060
City: DENVER State: CO Zip: 80202- Email: RUTHANN.MORSS@ENCANA.COM

For "Intent" 24 hour notice required, Name: BROWNING, CHUCK Tel: (970) 433-4139
COGCC contact: Email: chuck.browning@state.co.us

API Number 05-077-09171-00
Well Name: WHITE Well Number: 14-1(A14OU)
Location: QtrQtr: NENE Section: 14 Township: 8S Range: 96W Meridian: 6
County: MESA Federal, Indian or State Lease Number:
Field Name: GRAND VALLEY Field Number: 31290

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.356680 Longitude: -108.069490
GPS Data:
Data of Measurement: 03/12/2007 PDOP Reading: 2.4 GPS Instrument Operator's Name: BUCK HINKSON
Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems
 Other
Casing to be pulled: Yes No Top of Casing Cement:
Fish in Hole: Yes No If yes, explain details below
Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
Details:

Current and Previously Abandoned Zones

| Formation | Code | Perf. Top | Perf. Bottom | Date | Method of Isolation | Plug Depth |
|-----------|------|-----------|--------------|------|---------------------|------------|
| | | | | | | |

Total: 0 zone(s)

Casing History

| Casing Type | Size of Hole | Size of Casing | Weight Per Foot | Setting Depth | Sacks Cement | Cement Bot | Cement Top | Status |
|-------------|--------------|----------------|-----------------|---------------|--------------|------------|------------|--------|
| CONDUCTOR | 24 | 16 | 42 | 60 | 100 | 60 | 0 | VISU |
| SURF | 11 | 8+5/8 | 24 | 963 | 400 | 987 | 0 | VISU |
| 1ST | 7+7/8 | 5+1/2 | 17 | 6,184 | 700 | 6,188 | 4,265 | CBL |

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 4100 with 2 sacks cmt on top. CIBP #2: Depth 1050 with 2 sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Perforate and squeeze at 1013 ft. with 313 sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)
 Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:
 Set 20 sacks at surface
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
 Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: 09/09/2011
 *Wireline Contractor: MESA WIRELINE *Cementing Contractor: BJ SERVICES
 Type of Cement and Additives Used: CLASS G
 Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

1. LD 161 jts 2 3/8", 4.7# EUE J-55 tbg.
2. Set CIBP @ 4100'. Pressure test to 500 psi. Dump 2 sx cement on top.
3. Set CIBP @ 1050'. Dump 2 sx cement on top.
4. Perf sqz holes @ 1013'. Well went on vacuum.
5. Circ 130 bbls to clean up casing and surface casing.
6. ND BOPs and NU christmass tree.
7. Pump 64 bbls 15.8#, Class G cement (313 sx)
8. Dig out 6' around wellhead.
9. Cut off casing. Remove wellhead.
10. Pump 4 bbls Class G to top well off. (20 sx)
11. Weld on surface plate with 1" weep hole.
12. Weld on marker cap.
13. Back fill hole.
14. Well P&A'd 9/9/11.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: RUTHANN MORSS
 Title: REGULATORY ANALYST Date: _____ Email: RUTHANN.MORSS@ENCANA.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY:

| |
|--|
| |
|--|

Attachment Check List

| Att Doc Num | Name |
|-------------|----------------------|
| 400205704 | CEMENT JOB SUMMARY |
| 400205705 | WIRELINE JOB SUMMARY |
| 400205708 | WELLBORE DIAGRAM |
| 400205711 | OTHER |

Total Attach: 4 Files

General Comments

| <u>User Group</u> | <u>Comment</u> | <u>Comment Date</u> |
|--------------------------|-----------------------|----------------------------|
| | | |

Total: 0 comment(s)