

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

02/22/2012

Document Number:

661400068

Overall Inspection:

Unsatisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>289582</u>	<u>311696</u>		<u>KELLERBY, SHAUN</u>

Operator Information:OGCC Operator Number: 10079 Name of Operator: ANTERO RESOURCES PICEANCE CORPORATIONAddress: 1625 17TH ST STE 300City: DENVERState: COZip: 80202**Contact Information:**

Contact Name	Phone	Email	Comment
Alberts, Gerard	303-357-7341	jalberts@anteroresources.com	
Black, Jon	970 625 9922/(435) 237-1169	jblack@anteroresources.com	Operations Manager: Piceance Basin

Compliance Summary:QtrQtr: NWSW Sec: 15 Twp: 6S Range: 92W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
11/14/2011	661400021	PR	PR	U			N
03/13/2011	200300880	DG	DG	S			N
07/03/2007	200114140	CO	ND	S	I	P	N

Inspector Comment:

Cogcc staff was notified on 2/6/2012 that all corrective actions were complete for Noav Doc # 200330029. Staff conducted a follow up inspection on 2/17/12. Staff observed that the Saw dust that had originally left the pad surface was still lying on the berm and at the toe of the pad site. Noav is not closed at this time and violation remains unsatisfactory.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
289580	WELL	XX	01/27/2011	LO	045-13819	DIXON FED CA B1	
289581	WELL	XX	01/27/2011	LO	045-13818	DIXON FED CA B2	
289582	WELL	PR	06/15/2011	LO	045-13817	DIXON FED CA B3	X
289763	WELL	PR	11/16/2011	LO	045-13869	DIXON FED CA B7	
291432	WELL	DG	12/14/2011	LO	045-14373	Dixon Federal B10	
291433	WELL	XX	01/27/2011	LO	045-14372	DIXON FED CA B6	
291434	WELL	WO	12/14/2011	LO	045-14371	Dixon Federal B4	
291435	WELL	DG	12/14/2011	LO	045-14370	Dixon Federal B5	
291436	WELL	WO	12/14/2011	LO	045-14369	Dixon Federal B9	
291437	WELL	PR	09/15/2009	OW	045-14368	DIXON FEDERAL B8	
311696	LOCATION	XX	04/14/2009		-	Dixon Federal B Pad	
421653	WELL	PR	11/15/2011	GW	045-20424	DIXON FED CA B13	
421696	WELL	PR	12/20/2011	GW	045-20425	Dixon Federal B16	
421708	WELL	XX	02/27/2011		045-20427	DIXON FED CA B14	

Inspector Name: KELLERBY, SHAUN

421709	WELL	PR	12/19/2011	GW	045-20428	Dixon Federal B11	
421710	WELL	PR	11/15/2011	GW	045-20429	Dixon Federal B15	
421716	WELL	WO	09/07/2011		045-20432	Dixon Federal B12	

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>16</u>	Production Pits: _____
Condensate Tanks: <u>2</u>	Water Tanks: <u>4</u>	Separators: <u>4</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: <u>1</u>	Oil Pipeline: <u>1</u>	Water Pipeline: <u>1</u>
Gas Compressors: _____	VOC Combustor: <u>1</u>	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: <u>1</u>	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number: (S/U/V) _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 311696

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:

Group	User	Comment	Date
OGLA	kubeczkod	<p>GENERAL SITE COAs:</p> <p>Operator must implement best management practices to contain any unintentional release of fluids, including any fluids conveyed via temporary surface pipelines.</p> <p>Operator must ensure 110 percent secondary containment for any volume of fluids contained at well site during drilling and completion operations; including, but not limited to, construction of a berm or diversion dike, diversion/collection trenches within and/or outside of berms/dikes, site grading, or other comparable measures sufficiently protective of nearby surface water.</p> <p>The moisture content of any drill cuttings in a cuttings pit, trench, or pile shall be as low as practicable to prevent accumulation of liquids greater than de minimis amounts. At the time of closure, the drill cuttings must also meet the applicable standards of table 910-1.</p>	02/07/2011

Wildlife BMPs:**Stormwater:****Comment:****Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Well**

Facility ID: 289582 API Number: 045-13817 Status: PR Insp. Status: PR

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Inspector Name: KELLERBY, SHAUN

Cropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____

COGCC Comments

Comment	User	Date
Cogcc staff was notified on 2/6/2012 that all corrective actions were complete for Noav Doc # 200330029. Staff conducted a follow up inspection on 2/17/12. Staff observed that the Saw dust that had originally left the pad surface was still lying on the berm and at the toe of the pad site. Noav is not closed at this time and violation remains unsatisfactory.	kellerbs	02/22/2012

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
661400070	Saw dust at toe	http://cogcc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=2875826
661400071	Saw dust on berm	http://cogcc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=2875827