

FORM
6Rev
12/05State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

400289921

Date Received:

05/29/2012

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 10341

Contact Name: Karen LeBaron

Name of Operator: PUCKETT LAND COMPANY

Phone: (303) 763-1000

Address: 5460 S. QUEBEC STREET - STE #250

Fax: (303) 763-1040

City: GREENWOOD State: CO Zip: 80111

Email: klebaron@puckettland.com

For "Intent" 24 hour notice required, Name: LONGWORTH, MIKE Tel: (970) 812-7644

COGCC contact: Email: mike.longworth@state.co.us

API Number 05-103-10959-00

Well Name: FIGURE FOUR RANCH

Well Number: 499-14-83

Location: QtrQtr: SENE Section: 14 Township: 4S Range: 99W Meridian: 6

County: RIO BLANCO

Federal, Indian or State Lease Number:

Field Name: WILDCAT

Field Number: 99999

☒ Notice of Intent to Abandon☐ Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.703550 Longitude: -108.461931

GPS Data:

Date of Measurement: 07/30/2008 PDOP Reading: 2.9 GPS Instrument Operator's Name: ROBERT L. KAY

Reason for Abandonment: ☐ Dry ☐ Production for Sub-economic ☐ Mechanical Problems☒ Other Order of the COGCCCasing to be pulled: ☒ Yes ☐ No Top of Casing Cement: 1950Fish in Hole: ☐ Yes ☒ No If yes, explain details belowWellbore has Uncemented Casing leaks: ☐ Yes ☒ No If yes, explain details below

Details: Per agreement with Puckett Land Company and Encana Oil & Gas (USA) Inc., Encana proposes to plug & abandon the wellbore at this time.

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
COZZETTE	7410	7456			
COZZETTE-CORCORAN	7646	7734			
MANCOS B	9504	9560			
WILLIAMS FORK	6572	6717			

Total: 4 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
CONDUCTOR	24	20+1/163		80	220	80	0	VISU
SURF	14+3/4	9+5/8	36	1,900	1,719	1,900	0	CALC
1ST	8+3/4	5+1/2	17	9,606	1,573	9,606	5,600	CALC

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 9450 with 25 sacks cmt on top. CIBP #2: Depth 6520 with 25 sacks cmt on top.

CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.

CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 20 sks cmt from 5000 ft. to 4827 ft. Plug Type: CASING Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 100 sacks half in. half out surface casing from 1850 ft. to 1975 ft. Plug Tagged: ☒

Set 10 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☒ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1103 ☐ Yes ☐ No *ATTACH JOB SUMMARY

Technical Detail/Comments:

Per agreement with Puckett Land Company and Encana Oil & Gas (USA) Inc., Encana proposes to plug & abandon the wellbore at this time.

Well to be plugged per order of the COGCC - 1V-378

Well to be plugged first week of June 2012.

PLC apprEciates the state's prompt approval of this application.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Karen LeBaron

Title: Petroleum Landman Date: 5/29/2012 Email: klebaron@puckettland.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: KRABACHER, JAY Date: 6/4/2012

CONDITIONS OF APPROVAL, IF ANY:

Expiration Date: 12/3/2012

increased length (& cement quantity) at "stub plug" to overlap/envelope plug ~ 25'.

Attachment Check List

Att Doc Num	Name
400289921	FORM 6 INTENT SUBMITTED
400289925	PROPOSED PLUGGING PROCEDURE

Total Attach: 2 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	Both WBD's included as part of attached proposed plugging procedure.	5/30/2012 7:05:38 AM

Total: 1 comment(s)