

From: [Murray Herring](#)
To: KIM.SHUGAR@CI.LONGMONT.CO.US; [Chesson, Robert](#)
Subject: SERAFINI SOIL SAMPLE ANALYSIS
Date: Wednesday, July 18, 2012 9:34:03 AM
Attachments: [2012_07_18_08_43_01.pdf](#)

KIM & Bob

Attached are the results of the soil sample analysis on the Serafini drill pad. Five slit trenches were dug in the vicinity of the Terracon drill hole on the north side of the tank battery. Only one slit trench had soil with readings above state levels. This contaminated soil was removed and properly disposed of. The slit trench was filled with gravel and a four inch perforated plastic pipe six feet long. Any water entering the trench will be removed thru the pipe and tested. You will receive the results of these tests. A map of the well site and the location of the slit trenches will be forwarded as soon as the engineer completes a map from his notes. should you have any questions please let me know.

Murray