

FORM
6
Rev
12/05

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:
2237646

Date Received:
09/26/2012

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 51090 Contact Name: JOE DYK
 Name of Operator: LONE MOUNTAIN PRODUCTION CO Phone: (970) 858-7546
 Address: P O BOX 80965 Fax: (970) 858-4163
 City: BILLINGS State: MT Zip: 59108- Email: JOEDYK@AOL.COM

For "Intent" 24 hour notice required, Name: BROWNING, CHUCK Tel: (970) 433-4139
COGCC contact: Email: chuck.browning@state.co.us

API Number 05-077-08245-00 Well Number: 16
 Well Name: BAR X UNIT
 Location: QtrQtr: NWSW Section: 29 Township: 8S Range: 104W Meridian: 6
 County: MESA Federal, Indian or State Lease Number: 35265
 Field Name: BAR X Field Number: 5470

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.337250 Longitude: -109.018940
 GPS Data:
 Date of Measurement: 05/27/2011 PDOP Reading: 1.6 GPS Instrument Operator's Name: JOE DYK
 Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems
 Other DEMAND LETTER FROM STATE OF COLORADO
 Casing to be pulled: Yes No Estimated Depth: _____
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: PRESSURE TEST 4.5" CSG TO 200 PSI BEFORE CUTTING AT 377'.

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
DAKOTA	2696	2882			0
MORRISON	3057	3065			0

Total: 2 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	327	410	327	0	VISU
1ST	7+7/8	4+1/2	10.5	3,194	325	3,194	1,860	CALC

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 3045 with 2 sacks cmt on top. CIBP #2: Depth 2676 with 2 sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 132 sks cmt from 377 ft. to 0 ft. Plug Type: CASING Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)
 Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:
 Set _____ sacks at surface
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
 Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____
 *Wireline Contractor: _____ *Cementing Contractor: _____
 Type of Cement and Additives Used: _____
 Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: JOE DYK
 Title: PETROLEUM ENGINEER Date: 9/24/2012 Email: JOEDYK@AOL.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: KRABACHER, JAY Date: 10/5/2012

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: 4/4/2013

Attachment Check List

Att Doc Num	Name
2237646	FORM 6 INTENT SUBMITTED
2237647	WELLBORE DIAGRAM
2237648	OTHER

Total Attach: 3 Files

General Comments

User Group	Comment	Comment Date
Permit	old style comp. rept. #434782 sub. 10/06/85 meets form 5/5A requirements.	10/2/2012 7:04:57 AM

Total: 1 comment(s)