

CEMENT JOB REPORT



Shoe Test (Update Original Treatment Report for Primary Job)

Depth Drilled out of Shoe: 0 FT Target EMW: 0 LBS/GAL Actual EMW: 0 LBS/GAL
 Number of Times Tests Conducted: 0 Mud Weight When Test was Conducted: 0 LBS/GAL

Problems Before Job (I.E. Running Casing, Circulating Well, ETC)
 NONE

Problems During Job (I.E. Lost Returns, Equipment Failure, Bulk Delivery, Foaming, ETC)
 NONE

Problems After Job (I.E. Gas at Surface, Float Equipment Failed, ETC)
 NONE

EXPLANATION: TROUBLE SETTING TOOL, RUNNING CSG, ETC. PRIOR TO CEMENTING: NONE

PRESSURE/RATE DETAIL						EXPLANATION	
TIME HR:MIN.	PRESSURE - PSI		RATE BPM	Bbl. FLUID PUMPED	FLUID TYPE	SAFETY MEETING: BJ CREW <input checked="" type="checkbox"/> CO. REP. <input checked="" type="checkbox"/>	
	PIPE	ANNULUS				TEST LINES	4000 PSI
						CIRCULATING WELL - RIG <input checked="" type="checkbox"/> BJ <input type="checkbox"/>	
05:00	0	0	0	0	NA	ARRIVE ON LOCATION RIG RUNNING CSG RTS 530	
12:00	0	0	0	0	NA	SPOT TRUCKS	
13:15	0	0	0	0	NA	SAFETY MEETING	
13:36	4728	0	0	0	H2O	PSI TEST	
13:40	598	0	7	20	H2O	H2O SPACER	
13:43	693	0	7	20	H2O	MUD CLEAN 1	
13:48	704	0	7	20	H2O	H2O SPACER	
13:54	662	0	5	176	CMT	BATCH/WEIGH/PUMP LEAD @ 10.5 PPG	
14:30	480	0	5	53	CMT	WEIGH/PUMP TAIL @ 10.5 PPG	
14:45	0	0	0	0	H2O	SHUT DOWN DROP PLUG	
14:49	260	0	7	0	MUD	DISPLACEMENT	
14:56	578	0	6	40	MUD	CAUGHT CMT	
15:30	1218	0	3	235	MUD	SLOWED RATE	
15:33	2215	0	0		MUD	BUMPED PLUG FLOAT DID NOT HOLD FINAL LIFT 1243PSI LEFT 1500 PSI ON CSG	

BUMPED PLUG	PSI TO BUMP PLUG	TEST FLOAT EQUIP.	BBL.CMT RETURNS/ REVERSED	TOTAL BBL. PUMPED	PSI LEFT ON CSG	SPOT TOP OUT CEMENT	Service Supervisor Signature:
<input type="checkbox"/> Y <input checked="" type="checkbox"/> N	1200	<input type="checkbox"/> Y <input checked="" type="checkbox"/> N	0	534	1500	<input type="checkbox"/> Y <input checked="" type="checkbox"/> N	