



Freese, Steve <steve.freese@state.co.us>

Anschutz Obrien 5-61-33-57H approval to sidetrack

1 message

Ellsworth, Stuart <stuart.ellsworth@state.co.us>

Tue, Nov 13, 2012 at 9:19 AM

To: Stephen Freese <Steve.Freese@state.co.us>, Dirk Sutphin <Dirk.Sutphin@state.co.us>

Cc: "Diana Burn, P.E." <Diana.Burn@state.co.us>

Anschutz Obrien 5-61-33-57H Location: WELD NWNE 33 5N 61W 6 request to sidetrack

At the bend point the well was going in the wrong direction (MD 6400'). So they are going to pull back to 5000' and kick-off and restart the bend. The sidetrack paper work is in process. A verbal to proceed was give at 9:00 am 11-13-12

--

Stuart Ellsworth
COGCC Engineering Manager
303-894-2100 X5108