



JR Land Surveying, LLC

8114 Northstar Drive
Windsor, Colorado 80528
P. 970-576-4641

WELL LOCATION CERTIFICATE

THIS MAP DOES NOT REPRESENT A BOUNDARY SURVEY



Scale 1" = 1000'
1000
approximate scale

LEGEND
— found survey monument
— calculated dimension
(c)

In accordance with a request from Jay Knutson of EnCana Oil & Gas (USA) Inc., JR Land Surveying, LLC has determined the location of the **State 23-16 well** site to be SHL: 2441' FNL and 1461' FWL, (BHL 1980' FSL and 1980' FWL), as measured at ninety (90) degrees from the section lines of Sections 16, Township 3 North, Range 68 West of the 6th Principal Meridian, Weld County Colorado.

Proposed Surface Hole Data:

Latitude: N 40.22641° (BHL: 40.22401°)
Longitude: W 105.01212° (BHL: 105.01023°)
PDOP: 1.6

Nearest:

Building 1,226' southwest	Above Ground Utility 1,434' west
Public Road 1,453' west	Railroad 2,328' southeast
Property Line 206' south	Well Window: SHL is 387' outside
Existing Well: Runyan #1, 3,264' southwest	

I hereby certify that this Well Location Certificate was prepared by me or under my direct supervision on 6/13/2012 for and on behalf of EnCana Oil & Gas (USA) Inc. That it is not a Land Survey Plat or an Improvement Survey Plat and that it is not to be relied upon for establishment of fences, buildings, or other future improvement lines.

38219
6-13-2012
John Robert McGehee LS#38219
Well: State 23-16 W.C. LAND SURVEYOR

Notes:

- 1) Bearings and distances based on NAD 83 Colorado North State Plane Coordinate. using RTK GPS observations taken 6/4/12 by operator John Rice.
- 2) Conversion factor to ground (1.000285153).
- 3) Elevations based on NAVD 88 GPS heights and Geoid 2003 corrections.
- 4) See Location Drawing for visible improvements within 400 feet of Pad Site.
- 5) The surface use is a cultivated field.

NOTICE: According to Colorado law you must commence any legal action based upon any defect in this W.L.C. within three years after you first discover such defect. In no event may any action based upon any defect in this W.L.C. be commenced more than ten years from this said date of the certification shown hereon.