

FORM
6Rev
12/05

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

2238183

Date Received:

12/20/2012

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 10003

Contact Name: KEN CAMPBELL

Name of Operator: PANTHER ENERGY COMPANY INC

Phone: (918) 551-7112

Address: P O BOX 3105

Fax: (918) 583-5396

City: TULSA State: OK Zip: 74101

Email: KENC@PANTHERENERGY.US

For "Intent" 24 hour notice required,

Name: QUINT, CRAIG

Tel: (719) 767-8939

COGCC contact:

Email: craig.quint@state.co.us

API Number 05-063-06312-00

Well Name: NOAH

Well Number: 4-36

Location: QtrQtr: NENW Section: 36 Township: 7S Range: 43W Meridian: 6

County: KIT CARSON

Federal, Indian or State Lease Number:

Field Name: WILDCAT

Field Number: 99999

☐ Notice of Intent to Abandon☒ Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.402530

Longitude: -102.160870

GPS Data:

Date of Measurement: 09/04/2012

PDOP Reading: 1.6

GPS Instrument Operator's Name: GREG J. PETTIBONE

Reason for Abandonment:

☐ Dry☒ Production for Sub-economic☐ Mechanical Problems☐ OtherCasing to be pulled: ☐ Yes☒ No

Estimated Depth:

Fish in Hole: ☐ Yes☒ No

If yes, explain details below

Wellbore has Uncemented Casing leaks:

☐ Yes☒ No

If yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
NIOBRARA	1742	3052	09/14/2012		

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
CONDUCTOR	14+3/4	13+3/8	36	40	100	40	0	
SURF	12+1/4	9+5/8	36	430	100	430	0	
1ST	8+3/4	7	23	1,742	125	1,742	770	

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 1000 with 10 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at 481 ft. with 50 sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged: ☐

Set 20 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing

Plugging Date: 09/14/2012

*Wireline Contractor: PEAK WIRELINE SERVICES, INC

*Cementing Contractor: ALLIED OIL & GAS SERVICES, LLC

Type of Cement and Additives Used: CEMENT 2 %CC

Flowline/Pipeline has been abandoned per Rule 1103 ☐ Yes ☐ No

*ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: KEN CAMPBELL

Title: PRODUCTION MANAGER Date: 12/19/2012 Email: KENC@PANTHERENERGY.US

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: SUTPHIN, DIRK Date: 2/25/2013

CONDITIONS OF APPROVAL, IF ANY:

Attachment Check List

Att Doc Num	Name
2238183	FORM 6 SUBSEQUENT SUBMITTED
2238184	WIRELINE JOB SUMMARY
2238185	CEMENT JOB SUMMARY
2238186	OPERATIONS SUMMARY
2518176	WELLBORE DIAGRAM

Total Attach: 5 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	There is a note on the NOAV that the well was not logged.	2/21/2013 7:43:31 AM
Permit	No logs have been submitted.	2/15/2013 8:25:13 AM
Permit	This is a horizontal well.	1/23/2013 12:00:48 PM
Permit	Operator provided GPS and filled out form completely and provided a wellbore diagram.	1/23/2013 12:00:35 PM
Permit	On hold- Cement amount and placement differ from intent. Form not filled out completely. Missing wellbore diagram. As-drilled GPS for well location never taken.	1/3/2013 8:51:55 AM

Total: 5 comment(s)