

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

05/20/2013

Document Number:

670200469

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>280348</u>	<u>335437</u>	<u>BURGER, CRAIG</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number: 10071 Name of Operator: BARRETT CORPORATION* BILL

Address: 1099 18TH ST STE 2300

City: DENVER State: CO Zip: 80202

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		Shaun.Kellerby@state.co.us	NW Field Supervisor
Axelson, Aaron		aaxelson@billbarrettcorp.com	Production Foreman
Merry, Jesse		jmerry@billbarrettcorp.com	Area Superintendent

Compliance Summary:

QtrQtr: <u>NWNE</u>	Sec: <u>27</u>	Twp: <u>6S</u>	Range: <u>92W</u>				
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/20/2011	200309950	PR	PR	S			Y
05/05/2009	200212627	PR	PR	S			N
11/19/2007	200123245	CO	PR	S	I		N
06/14/2006	200097784	CO	PR	S		P	N
03/08/2006	200088742	PR	WO	S		P	N
11/29/2005	200085872	PR	PR	U		P	N

Inspector Comment:

Spoke to pumper. He informed me he will fix minor leak at tank battery fitting, clean up parafin at separators, and assess casing valve.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
280348	WELL	PR	04/29/2006	GW	045-11239	STRANAHAN 31C-27-692	<input checked="" type="checkbox"/>
280349	WELL	PR	04/30/2006	GW	045-11240	STRANAHAN 31A-27-692	<input checked="" type="checkbox"/>
280350	WELL	PR	12/10/2008	GW	045-11241	STRANAHAN 41A-27-692	<input checked="" type="checkbox"/>
280351	WELL	PR	05/01/2006	GW	045-11242	STRANAHAN 41C-27-692	<input checked="" type="checkbox"/>

Equipment:**Location Inventory**

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Signs/Marker:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	Satisfactory			
WELLHEAD	Satisfactory			
BATTERY	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
IGNITOR/COMBUST OR	Satisfactory	wire fence		
WELLHEAD	Satisfactory	cattle panel		
SEPARATOR	Satisfactory	cattle panel		
TANK BATTERY	Satisfactory	cattle panel		

Equipment:

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Gathering Line	1	Satisfactory			
Bird Protectors	7	Satisfactory			
Plunger Lift	4	Satisfactory			
Horizontal Heated Separator	4	Unsatisfactory	Containment provided. Parafin accumulation at scrubber pot vent tubing on both sides.	Clean up and prevent discharge to containment area.	06/14/2013
Emission Control Device	1	Satisfactory			
Deadman # & Marked	4	Satisfactory	At least two markers down.		

Facilities:		<input type="checkbox"/> New Tank		Tank ID: _____	
Contents	#	Capacity	Type	SE GPS	
METHANOL	1	<50 BBLS	STEEL AST	39.503530,-107.649960	
S/U/V:	Satisfactory		Comment:		
Corrective Action:				Corrective Date:	
Paint					
Condition	Adequate				
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment					
Facilities:		<input type="checkbox"/> New Tank		Tank ID: _____	
Contents	#	Capacity	Type	SE GPS	
CONDENSATE	4	200 BBLS	HEATED STEEL AST	39.503630,-107.649840	
S/U/V:	Unsatisfactory		Comment: One pipe fitting appears to be dripping.		
Corrective Action: Maintain equipment leak free.				Corrective Date: 06/14/2013	
Paint					
Condition	Adequate				
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment: Erosion undermining berm at north side.					
Venting:					
Yes/No		Comment			
YES		Bradenhead valves open and one casing valve hissing.			
Flaring:					
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date	
Ignitor/Combustor	Satisfactory				

Predrill

Location ID: 335437

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:****CA:****Date:****Wildlife BMPs:****Comment:****CA:****Date:****Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment:**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 280348 Type: WELL API Number: 045-11239 Status: PR Insp. Status: PR

Producing Well

Comment: plunger lift

Facility ID: 280349 Type: WELL API Number: 045-11240 Status: PR Insp. Status: PR

Inspector Name: BURGER, CRAIG

Producing Well

Comment: plunger lift. Casing valve is hissing.

Facility ID: 280350 Type: WELL API Number: 045-11241 Status: PR Insp. Status: PR

Producing Well

Comment: plunger lift

Facility ID: 280351 Type: WELL API Number: 045-11242 Status: PR Insp. Status: PR

Producing Well

Comment: plunger lift

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

Water Well:

DWR Receipt Num: Owner Name: GPS : Lat Long

Field Parameters:

Sample Location:

Complaint:				
Tracking Num	Category	Assigned To	Description	Incident Date
200080570	ODOR	KRABACHER, JAY	<p>SEE FORM 18 (APPROVED) DOC # 200076851. MS. B CALLED ON ODORS/FUMES FROM AREA WELLS -- ESPECIALLY THE LOUTHAN AND FERGUSON PADS. NOAVS ISSUED ON THOSE RE: CONDENSATE REMOVAL AND FLUID LEVEL NOT LEAVING 2' OF FREEBOARD. 11/19 MS. B CALLED RE: ODOR FROM THE STRANAHAN PAD. JK RETURNED CALL 11/21 & VISITED STRANAHAN LOC 11/29. NOTED < 2' FREEBOARD AT STRANAHAN AND LOUTHAN AND EPPERLY (BEING DRILLED) PADS. SENT LETTER TO NEW PICEANCE PROJECT MANAGER (CHRIS HANSEN) ABOUT THESE -- "NEXT TIME THE COGCC WILL ISSUE NOAV". FLOW-TESTER AT LOUTHAN STARTED LOWERING PIT FLUID LEVEL IMMEDIATELY -- MUCH LOWER LATER IN THE DAY. ONI ALSO ASKED ABOUT THE "STUFF" ON LOUTHAN PIT SURFACE. J K CALLED BOB CHESSON AND RECEIVED THE "GUAR GUM TUTORIAL" WHICH HE RELAYED TO MS. B. --> THE STUFF ON PIT SURFACES IS MOSTLY ENVIRONMENTALLY BENIGN, THO' SOMETIMES ODIFEROUS -- GUAR GUM FOR INCREASING DOWNHOLE FRAC PRESSURE AND TO HELP 'CARRY' THE SAND. ALSO ENZYME TO BREAK-DOWN THE GUAR. SEEING AS HOW THE WEATHER'S COLD, THE BREAKING DOWN HAS BEEN SLOWED. 12/5 MS. B LEFT MESSAGE: A "DIFFERENT" SORT OF STENCH, STILL "VERY BAD". 12/6 CALLED RE: ODOR, THE "BENZENE SMELL". J K CALLED KEN KUHN WHO HAD BEEN CALLED BY MS. B -- SAID HE HAD HIS PUMPER AND OTHER FIELD CREW ON THE ALERT FOR ANYTHING UNUSUAL. KEN SAID THAT THERE WAS NOTHING OUT OF THE ORDINARY GOING ON IN THE O B VICINITY. MS. B CALLED 12:30 PM AND WAS VERY UPSET. POB 347 SILT 81652. SHE FELT THAT THE GAS CO. IS TRAMPLING OVER ALL PROPERTY OWNERS IN THE AREA AND THERE WAS NOTHING THAT COULD BE DONE ABOUT IT. THE PRISTINENESS OF THE CANYON/VALLEY SHE OWNS IS COMPROMISED. NO-ONE IS EXPRESSING INTEREST IN HER PROPERTY FOR SALE. HOWEVER, SHE DID ASK THAT I TRY TO PROCURE (EITHER FROM OPR OR GAR CO) FULL-TIME AIR-MONITORING EQUIPMENT (OUTSIDE) AND AN AIR-POLLUTION CONTROL DEVICE FOR THE INSIDE. RECOMMENDED A COUPLE OUTLETS AND BRANDS (IN RIFLE: "MOUNTAIN AIR" AND THE AERUS BRAND). PERHAPS THE AERUS SILENT HEPA FILTER SYSTEM. J K LEFT MESSAGE WITH TROY SCHINDLER AND JIM FELTON REGARDING THIS. 12/29 PM: MESSAGE LEFT: STRONG ODOR IN A.M. AND ALSO AT ABOUT 4:30 PM. "ENCANA USES CLOSED EVAP PITS & SEPARATORS" -- WHY DOESN'T BBC DO THE SAME? J K LEFT MSG ~ 630 PM. TALKED W/KEN KUHN 12/30: KEN SAID THAT BBC HAS NEW CMPLTNS SUPERVISOR: BILL KELLY (307) 360-6266. 2/1/06: J K HAS BEEN 'TOURING' CHIPPERFIELD AREA APPROX ONCE / WEEK (LATEST: 1/30/06). BOTH LOUTHAN AND FERGUSON PITS RECLAIMED / LOC'S CONTOURED. NO NEW WELLS IN IMMEDIATE VICINITY FOR NOW.</p>	12/06/2005

Emission Control Burner (ECB): Y

Comment: _____

Pilot: ON Wildlife Protection Devices (fired vessels): YES**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____ CA _____ CA Date _____

Waste Material Onsite? Pass CM _____ CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____ CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? In CM _____ CA _____ CA Date _____

Guy line anchors removed? _____ CM _____ CA _____ CA Date _____

Guy line anchors marked? _____ CM _____ CA _____ CA Date _____

1003b. Area no longer in use? Fail Production areas stabilized? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? Pass Segregated soils have been replaced? _____**RESTORATION AND REVEGETATION**Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? PComment: Area appears larger than necessary for production.Overall Interim Reclamation Fail**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Inspector Name: BURGER, CRAIG

Access Roads Regraded _____ Contoured _____ Culverts removed _____
Gravel removed _____
Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____
Compaction alleviation _____ Dust and erosion control _____
Non cropland: Revegetated 80% _____ Cropland: perennial forage _____
Weeds present _____ Subsidence _____
Comment: _____
Corrective Action: _____ Date _____

Overall Final Reclamation

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Waddles	Pass			
Ditches	Pass	Gravel	Pass			
Gravel	Pass	Culverts	Pass			
		Blankets	Pass			
Compaction	Pass	Rip Rap	Pass			

S/U/V: **Unsatisfactory** Corrective Date: **06/14/2013**

Comment: **Erosion is undermining berm at north side of tank battery.**

CA: **Provide and maintain adequate erosion control BMP's.**