

|            |                  |
|------------|------------------|
| Well:      | EnCana Fee 24-9B |
| Pad:       | K19CNE           |
| API No:    | 05045207600000   |
| Permit No: |                  |

### **Bradenhead Pressure Report Following Primary Cement Job**

|                |            |
|----------------|------------|
| Date Cemented: | 03/06/2013 |
| Plug Bumped:   | YES        |

|                                                     |        |         |
|-----------------------------------------------------|--------|---------|
| Annular Fluid Level After Job (Static or Falling?): | STATIC |         |
| If falling, barrels of mud added until stabilized:  | N/A    | barrels |

|               |                             |
|---------------|-----------------------------|
| WOC Time:     | 6 hours                     |
| Bond Log Run: | Temp log ran in lieu of CBL |

|                   |     |
|-------------------|-----|
| Casing Slips Set: | YES |
|-------------------|-----|

### **Bradenhead Pressures**

|         |   |      |
|---------|---|------|
| 6 hrs:  | 0 | psig |
| 12 hrs: | 0 | psig |
| 24 hrs: | 0 | psig |
| 48 hrs: | 0 | psig |
| 72 hrs: | 0 | psig |

### **Comments**

The well was cemented with full returns and the annulus held for 4 hours prior to setting casing slips. A CBL was performed when the rig moved off the pad. Bradenhead pressure has remained at 0 psi to date.



|     |         |         |
|-----|---------|---------|
| YES | STATIC  | 6 hours |
| NO  | FALLING |         |

Temp log ran in lieu of CBL