

FORM

19

Rev 6/99

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303)894-2100 Fax: (303)894-2109



FOR OGCC USE ONLY

RECEIVED  
7/25/2013

### SPILL/RELEASE REPORT

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

Spill report taken by:

FACILITY ID:

#### OPERATOR INFORMATION

Name of Operator: SG Interests I Ltd	OGCC Operator No: 77330	Phone Numbers
Address: 1485 Florida Road, C202		No: 970-385-0696
City: Durango	State: CO Zip: 81301	Fax: 970-385-0636
Contact Person: Catherine Dickert		E-Mail: cdickert@sginterests.com

#### DESCRIPTION OF SPILL OR RELEASE

Date of Incident: 06/27/2013	Facility Name & No.: 324472	County: Gunnison
Type of Facility (well, tank battery, flow line, pit): well pad with generator		QtrQtr: NENE Section: 26
Well Name and Number: Federal 11-90-26 #1		Township: 11s Range: 80w
API Number: 05-051-06060		Meridian: 6

Specify volume spilled and recovered (in bbls) for the following materials:

Oil spilled: \_\_\_\_\_ Oil recov'd: \_\_\_\_\_ Water spilled: \_\_\_\_\_ Water recov'd: \_\_\_\_\_ Other spilled: 5 gallons Other recov'd: 5 gallons

Ground Water impacted?  Yes  NoSurface Water impacted?  Yes  NoContained within berm?  Yes  No

Area and vertical extent of spill: 4x6' x 1' deep

Current land use: range land with gas facilities

Weather conditions: dry

Soil/geology description: Fughes loam

IF LESS THAN A MILE, report distance IN FEET to nearest.... Surface water: 240 wetlands: 240 buildings: 5200

Livestock: 110 water wells: 6900 Depth to shallowest ground water: &gt;49

Cause of spill (e.g., equipment failure, human error, etc.): leak of lube oil on generator, equip failure Detailed description of the spill/release incident:

Generator on location leaked lube oil. Much of the oil was misted on the generator itself by the fan. About 5 gallons in total was spilled. There was some soil staining as described above.

#### CORRECTIVE ACTION

Describe immediate response (how stopped, contained and recovered):

The generator was not operated after spill discovery. The equipment was removed from location. The soil was collected and placed on a tarp for treatment.

Describe any emergency pits constructed:

None.

How was the extent of contamination determined:

Visual inspection.

Further remediation activities proposed (attach separate sheet if needed):

The gravel beneath the generator was dug out approx. 6ftx2' deep and replaced with new gravel. The old dirt and gravel was contained on a tarp and treated on location with microorganisms. Treatment will continue for 1 month and then it will be sampled. Any further remediation will be determined at that time.

Describe measures taken to prevent problem from reoccurring:

The equipment was removed from the location. If a generator is still needed, a properly working unit will be used.

#### OTHER NOTIFICATIONS

List the parties and agencies notified (County, BLM, EPA, DOT, Local Emergency Planning Coordinator or other).

Date	Agency	Contact	Phone	Response
07/23/2013	CDPHE	Ann Nedrow	hotline #	no report issued, nothing further req.
06/27/2013	BLM	Thane Stranathan	(970) 240-5304	sundry notice for cleanup required

Spill/Release Tracking No: \_\_\_\_\_