

RECEIVED  
8/9/2013

SourceGas  
600 12th Street  
Suite 300  
Golden, CO 80401  
303 243 3400  
303 243 3602 Fax  
www.SourceGas.com



August 9, 2013

Lonny Bagley.  
Deputy State Director for Energy, Lands and Minerals  
2850 Youngfield Street  
Lakewood, Colorado 80215

RE: Rocky Mountain Natural Gas LLC  
Report of Undesirable Event (NTL-3A)

Mr. Bagley,

Please find enclosed a Form NTL-3A, Report of Undesirable Event, for a Rocky Mountain Natural Gas, LLC natural gas storage well pad, API 05-097-05067. The release was verbally reported to Carlos Lujan of the State of Colorado Oil and Gas Conservation Commission via telephone at approximately 11:00 on Thursday, August 1, 2013.

If you have questions, please contact me at 303.243.3584 or, [nathan.knell@sourcegas.com](mailto:nathan.knell@sourcegas.com).

Sincerely,

A handwritten signature in black ink, appearing to read "Nathan Knell".

Nathan Knell  
Manager, EHS&T

Cc: Alex Fisher (COGCC)  
Carlos Lujan (COGCC)  
Steve Ficklin (BLM)  
Karla Mobley (USFS)

**BUREAU OF LAND MANAGEMENT  
REPORT OF UNDESIRABLE EVENT (NTL-3A)**

Operator: Rocky Mountain Natural Gas, LLC Date/Time of Occurrence: Unknown

Field/Unit Name: Wolf Creek Date/Time BLM Notified: verbal notification provided at ~11:00 on August 7, 2013.

Location: Pitkin, County, Colorado; SW ¼ NE ¼ Sec: 1, T. 9 S., R. 90 W.

Lease No. 14080001181141, Surface Ownership:  Federal  Indian  Fee  State  
(Place an "X" to mark ownership.)

Type of Event: Potential Historical Release

Cause of Event: At the request of the Bureau of Land Management (BLM), Rocky Mountain Natural Gas, LLC (RMNG) is conducting a seep investigation at the down gradient side of the Wolf Creek Unit #5 well pad. In conjunction with the seep investigation, a series of piezometers were installed in July, 2013, to establish groundwater quality parameters. Results from water samples collected revealed very low levels of hydrocarbon impacts in Piezometers #3 & #9 (see Attachment A). Results from samples collected at piezometers further down gradient were non-detect for all analytes sampled.

Time Required To Control Event (hrs.): Not Applicable

Volumes Discharged or Consumed: Unknown

Volumes Recovered: None

Action Taken to Control Event/Resultant Damage/Clean-Up Procedures/Dates:

An additional water sample from the piezometers with the observed hydrocarbon results (Piezometers #3 & #9) were collected on August 6, 2013. The samples are being analyzed for GRO and DRO. An additional water sample was collected from these two piezometers and submitted to an accredited laboratory for a finger print analysis. Results from these samples will determine if observed hydrocarbon are Biogenic or Petrogenic in nature, or both.

Cause/Extent of Personnel Injury: Not Applicable


Governmental Agencies Notified (Federal/State/Local): Colorado Oil and Gas Conservation Commission, Colorado Department of Public Health and Environment, United States Forest Service and Bureau of Land Management





bing™

© 2013 Microsoft Corporation




DISCLAIMER: This Geographic Information System (GIS) and its components are designed as a source of reference for answering inquiries, for planning and for modeling. GIS is not intended, nor does it replace legal description information in the chain of title and other information contained in official government records such as the County Clerk and Recorders office or the courts. In addition, the representations of locations in this GIS cannot be substituted for actual legal surveys.

Attachment A - Piezometer 9 Location  
 Location: Wolf Creek Well 5,  
 NE 1/4 Sec.1, T9S, R90W  
 Rocky Mountain Natural Gas, LLC

**Legend**

- Piezometer
- PIEZOMETER**



Comments:

