

FORM

19

Rev 6/99

State of Colorado Oil and Gas Conservation Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303)894-2100 Fax:(303)894-2109

FOR OGCC USE ONLY

RECEIVED
8/14/2013

SPILL/RELEASE REPORT

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

Spill report taken by:

FACILITY ID:

OPERATOR INFORMATION

Name of Operator: Bill Barrett Corporation OGCC Operator No: 10071
 Address: 1099 18th Street, Suite 2300
 City: Denver State: CO Zip: 80202
 Contact Person: Rusty Frishmuth

Phone Numbers

No: 303-293-9100
 Fax: 303-291-0420
 E-Mail: rfrishmuth@billbarrettcorp.com

DESCRIPTION OF SPILL OR RELEASE

Date of Incident: 8-11-13 Facility Name & No.: Siebring pad, COGCC Facility #428174 County: Weld
 Type of Facility (well, tank battery, flow line, pit): well pad QtrQtr: SENE Section: 32
 Well Name and Number: N/A Township: 5N Range: 63W
 API Number: N/A Meridian: 6

Specify volume spilled and recovered (in bbls) for the following materials:

Oil spilled: 8-10 bbls Oil recov'd: 8-10 bbls Water spilled: 0 Water recov'd: _____ Other spilled: 0 Other recov'd: _____Ground Water impacted? ☐ Yes ☒ NoSurface Water impacted? ☐ Yes ☒ NoContained within berm? ☐ Yes ☒ NoArea and vertical extent of spill: 150 x 170Current land use: AgriculturalWeather conditions: RainSoil/geology description: Dacono clay loam, 0 to 1 percent slopes

IF LESS THAN A MILE, report distance IN FEET to nearest.... Surface water: 730 ft N wetlands: 3,900 ft NE buildings: 1,936 ft NW
 Livestock: Unknown water wells: 742 ft N Depth to shallowest ground water: est 30' bgs

Cause of spill (e.g., equipment failure, human error, etc.): Human error Detailed description of the spill/release incident:
Side hatch of temporary storage tank failed to be completely latched. Workers on site noticed that tank was losing fluid.

CORRECTIVE ACTION

Describe immediate response (how stopped, contained and recovered):

Flow to tank was stopped and hatch was properly secured. Oil predominantly floated on standing water in cornfield from recent heavy rains. This allowed for nearly complete recovery of all oil released.

Describe any emergency pits constructed:

None

How was the extent of contamination determined:

Visual observation.

Further remediation activities proposed (attach separate sheet if needed):

Soil samples collected 8-12-13, will remediate as needed is samples exceed Table 910 standards.

Describe measures taken to prevent problem from reoccurring:

Hatch latched, site workers counseled on proper pre-job site walk.

OTHER NOTIFICATIONS

List the parties and agencies notified (County, BLM, EPA, DOT, Local Emergency Planning Coordinator or other).

Date	Agency	Contact	Phone	Response
8-12-13	Weld County DPHE	Troy Swain	970-304-6411	Initial notification
8-13-13	Weld County OEM	Gracie Marquez & Roy Rudisill	970-304-6540	Initial notification

Spill/Release Tracking No: **2145798**