



DE ET OE ES

Document Number:

400459051

Date Received:

07/29/2013

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.
 A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 75027 Contact Name: Wayne Mahon
 Name of Operator: ROSEWOOD RESOURCES INC Phone: (970) 630-6834
 Address: 2101 CEDAR SPRINGS RD STE 1500 Fax: (970) 848-2245
 City: DALLAS State: TX Zip: 75201 Email: wmahon@rosewd.com
For "Intent" 24 hour notice required, Name: SCHURE, KYM Tel: (970) 520-3832
COGCC contact: Email: kym.schure@state.co.us

API Number 05-125-06248-00 Well Number: 1-22
 Well Name: GOFF
 Location: QtrQtr: N2NE Section: 22 Township: 3N Range: 46W Meridian: 6
 County: YUMA Federal, Indian or State Lease Number: _____
 Field Name: BUCKBOARD Field Number: 7680

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.217934 Longitude: -102.495149
 GPS Data:
 Date of Measurement: 10/26/2010 PDOP Reading: 2.1 GPS Instrument Operator's Name: Nate Chesley
 Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems
 Other _____
 Casing to be pulled: Yes No Estimated Depth: _____
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
NIOBRARA	2704	2716			

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	433	400	433	0	CALC
1ST	7+7/8	4+1/2	9.5	2,839	125	2,840	2,239	CALC

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 2654 with 2 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at 483 ft. with 110 sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

Fill 4 1/2" csg and 8 5/8" surf csg from 483' to surf. Cut off csg 5' below ground level, weld plate and backfill.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Stacey Owston

Title: Office Manager Date: 7/29/2013 Email: sowston@rosewd.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: SUTPHIN, DIRK Date: 9/12/2013

CONDITIONS OF APPROVAL, IF ANY: _____

Expiration Date: 3/11/2014

COA Type

Description

1) Provide 24 hour notice of MIRU to Kym Schure at 970-520-3832 or e-mail at Kym.Schure@state.co.us.

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
400459051	FORM 6 INTENT SUBMITTED
400459268	WELLBORE DIAGRAM

Total Attach: 2 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	Completion or recompletion report. doc. # 653222 dated 3/15/1979	7/30/2013 5:24:48 AM

Total: 1 comment(s)