



STATE OF
COLORADO

Andrews - DNR, Doug <doug.andrews@state.co.us>

Fwd: Denny/Smock Form 2As in process

1 message

Young - DNR, Rob <rob.young@state.co.us>
To: Doug Andrews - DNR <doug.andrews@state.co.us>

Thu, Oct 10, 2013 at 11:28 AM

FYI

----- Forwarded message -----

From: **Young - DNR, Rob** <rob.young@state.co.us>
Date: Tue, Aug 6, 2013 at 11:06 AM
Subject: Denny/Smock Form 2As in process
To: jcinamon@dakotaexploration.com

Hi Jake,

The following are my comments on the proposed locations in 11N 58W sections 2 and 11.

400424450 - Smock 3-2-11-59H -

No production facilities are listed for the well and there is no indication that the production will flow to another location.

There is a dirt road shown on the Location Drawing and it does not appear to be the road indicated on the Access Road Map. I would like to see an integrated Access Road Map for all of these locations that represents a realistic plan to access the locations with minimal disturbance and in accordance with Rule 1002.e.(4). The road comment applies to all of these locations.

400424448 - Smock 1-2-11-59H -

Access road comment only.

400424449 - Smock 2-2-11-59H -

No production facilities are listed for the well and there is no indication that the production will flow to another location.

This location appears to have greater than 10% slope and therefore requires Construction Layout Drawings, or relocation.

400424451 - Smock 4-2-11-59H -

No production facilities are listed for the well and there is no indication that the production will flow to another location.

There is a road shown on the Location Drawing that does not match the Access Road Map.

400424452 - Denny 1-11-11-59H -

This location appears to have greater than 10% slope and therefore requires Construction Layout Drawings, or relocation.

400424453 - Denny 2-11-11-59H -

No production facilities are listed for the well and there is no indication that the production will flow to another location.

400424454 - Denny 3-11-11-59H -

No production facilities are listed for the well and there is no indication that the production will flow to another

location.

There is a road shown on the Location Drawing that does not match the Access Road Map.

400424455 - Denny 4-11-11-59H -

No production facilities are listed for the well and there is no indication that the production will flow to another location.

The Access Road Map shows a proposed road into the location from due east. The Location Drawing shows an existing road on the north side of the location.

Let me know if you have any questions or concerns, thanks,

—

Robert J. Young
Oil and Gas Location Assessment Specialist
Colorado Oil and Gas Conservation Commission
1120 Lincoln Street, Suite 801
Denver, CO 80023
 [\(303\) 894-2100 X 5144](tel:(303)894-2100)

—

Robert J. Young
Oil and Gas Location Assessment Specialist
Colorado Oil and Gas Conservation Commission
1120 Lincoln Street, Suite 801
Denver, CO 80023
 [\(303\) 894-2100 X 5144](tel:(303)894-2100)