

FORM

19

Rev 6/99

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303)894-2100 Fax:(303)894-2109



FOR OGCC USE ONLY

**RECEIVED**  
 10/29/2013

## SPILL/RELEASE REPORT

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

Spill report taken by:

FACILITY ID:

### OPERATOR INFORMATION

Name of Operator: <u>Bill Barrett Corporation</u>	OGCC Operator No: <u>10071</u>	Phone Numbers
Address: <u>1099 18th St., Ste 2300</u>		No: <u>303-293-9100</u>
City: <u>Denver</u>	State: <u>CO</u> Zip: <u>80202</u>	Fax: <u>303-291-0420</u>
Contact Person: <u>Rusty Frishmuth</u>		E-Mail: <u>rfrishmuth@billbarrettcorp.com</u>

### DESCRIPTION OF SPILL OR RELEASE

Date of Incident: <u>10-19-13</u>	Facility Name & No.: <u>Anschutz Windmill 4-22H-5-62</u>	County: <u>Weld</u>
Type of Facility (well, tank battery, flow line, pit): <u>Well</u>		QtrQtr: <u>SESE</u> Section: <u>22</u>
Well Name and Number: <u>Anschutz winmill 4-22H-5-52</u>		Township: <u>5N</u> Range: <u>62W</u>
API Number: <u>05-123-33001</u>		Meridian: <u>6</u>
Specify volume spilled and recovered (in bbls) for the following materials:		
Oil spilled: <u>5</u>	Oil recov'd: <u>0</u>	Water spilled: <u>0</u> Water recov'd: <u>0</u> Other spilled: <u>0</u> Other recov'd: <u>0</u>
Ground Water impacted? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Surface Water impacted? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Contained within berm? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Area and vertical extent of spill: <u>135'</u> x <u>140'</u>	
Current land use: <u>Rangeland</u>	Weather conditions: <u>Clear/Sunny</u>	
Soil/geology description: <u>Valent Sand</u>		
IF LESS THAN A MILE, report distance IN FEET to nearest.... Surface water: <u>11,415.84</u> wetlands: <u>11,415.84</u> buildings: <u>18,159.09</u>		
Livestock: <u>200'</u> water wells: <u>2,282.84'</u> Depth to shallowest ground water: <u>30'</u>		
Cause of spill (e.g., equipment failure, human error, etc.): <u>Seal failure in stuffing box</u> Detailed description of the spill/release incident:		
High pressure from midstream partner's sales line caused increased pressure at the well. this increased pressure caused seals at stuffing box to fail. Oil spill sprayed from stuffing box covering location with fine mist or oil.		

### CORRECTIVE ACTION

Describe immediate response (how stopped, contained and recovered):  
 The well was shut in upon discovery and the released oil was immediately contained within the vicinity of the well head.

Describe any emergency pits constructed:  
 None

How was the extent of contamination determined:  
 Calculations from well production determined that approximately 5 barrels was released from the stuffing box.

Further remediation activities proposed (attach separate sheet if needed):  
 All impacted soil will be excavated and analytical testing of the remaining soil will be conducted to verify soils are in compliance with COGCC 910-1 concentration level.

Describe measures taken to prevent problem from reoccurring:  
 Murphy switch will be moved towards the well head to ensure that pressure build up well shut down before stuffing box failure.

### OTHER NOTIFICATIONS

List the parties and agencies notified (County, BLM, EPA, DOT, Local Emergency Planning Coordinator or other).

Date	Agency	Contact	Phone	Response
10-19-13	Weld County OEM	roy Rudisill	303-304-6540	Pending
10-19-13	State of Colorado Land Board	Matt Pollart	970-454-5279	Pending

Spill/Release Tracking No: **2146802**