

FORM
6Rev
12/05

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

400513250

Date Received:

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 100185

Contact Name: RUTHANN MORSS

Name of Operator: ENCANA OIL & GAS (USA) INC

Phone: (720) 876-5060

Address: 370 17TH ST STE 1700

Fax: (720) 876-6060

City: DENVER State: CO Zip: 80202-

Email: RUTHANN.MORSS@ENCANA.COM

For "Intent" 24 hour notice required,

Name: BROWNING, CHUCK

Tel: (970) 433-4139

COGCC contact:

Email: chuck.browning@state.co.us

API Number 05-077-08485-00

Well Name: MOONEY

Well Number: 2-10 (PL10NE)

Location: QtrQtr: NENE Section: 10 Township: 10S Range: 95W Meridian: 6

County: MESA

Federal, Indian or State Lease Number: 35745

Field Name: PLATEAU

Field Number: 69300

☒ Notice of Intent to Abandon☐ Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.208450

Longitude: -107.974100

GPS Data:

Date of Measurement: 07/24/2006

PDOP Reading: 2.9

GPS Instrument Operator's Name: Buck Hinkson

Reason for Abandonment:

☐ Dry☒ Production for Sub-economic☐ Mechanical Problems☐ OtherCasing to be pulled: ☐ Yes☒ No

Estimated Depth:

Fish in Hole: ☐ Yes☒ No

If yes, explain details below

Wellbore has Uncemented Casing leaks: ☐ Yes☒ No

If yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Code	Perf. Top	Perf. Bottom	Date	Method of Isolation	Plug Depth

Total: 0 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	310	230	310	0	
1ST	7+7/8	4+1/2	10.5	5,321	300	5,321	4,400	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 4567 with 2 sacks cmt on top. CIBP #2: Depth 410 with 2 sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at 360 ft. with 132 sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged: ☐

Set 15 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☒ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1103 ☐ Yes ☐ No *ATTACH JOB SUMMARY

Technical Detail/Comments:

ENCANA REQUESTS APPROVAL TO PLUG AND ABANDON THIS WELL USING THE FOLLOWING PROCEDURE:

1. POOH WITH 2 3/8" TBG.
2. RUN CBL FROM PBTD (5238') TO 4000' TO CONFIRM TOC. NEW TOC DETERMINED TO BE 5064' INSTEAD OF 4400' FROM GEARHART & OWENS CBL.
3. SET 4 1/2" CIBP @ 4567'. TEST CASING TO 500 PSI. DUMP BAIL 2 SX CEMENT ON TOP OF PLUG.
4. SET 4 1/2" CIBP @ 410'. TEST CASING TO 500 PSI. DUMP BAIL 2 SX CEMENT ON TOP OF PLUG.
5. PERF @ 360' WITH 4 SPF. ESTABLISH CIRCULATION DOWN 4 1/2" CASING UP BRADENHEAD VALVE.
6. MIX AND PUMP 132 SX CLASS G NEAT CEMENT 15.8PPG TO SURFACE BEHIND 4 1/2" CASING.
7. CEMENT SHOULD BE VISIBLE AT SURFACE. IF NOT, BACK FILL HOLE WITH CEMENT TO SURFACE.
8. CUT OFF WELLHEAD 4' BELOW GRADE AND WELD ON P&A MARKER.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: RUTHANN MORSS
Title: REGULATORY ANALYST Date: _____ Email: RUTHANN.MORSS@ENCANA.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: _____

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

400513294	WELLBORE DIAGRAM
400513296	WELLBORE DIAGRAM

Total Attach: 2 Files

General Comments

User Group

Comment

Comment Date

--	--	--

Total: 0 comment(s)