

State of Colorado  
Oil and Gas Conservation Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303)894-2100 Fax: (303)894-2109

FOR OGCC USE ONLY

RECEIVED  
11/18/2013

### SPILL/RELEASE REPORT

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

Spill report taken by:

FACILITY ID:

#### OPERATOR INFORMATION

Name of Operator: Encana Oil & Gas (USA) Inc.	OGCC Operator No: 100185	Phone Numbers
Address: 143 Diamond Avenue		No: 970.285.2735
City: Parachute	State: CO Zip: 81635	Fax: 970.285.2705
Contact Person: Charlie Jensen, Environmental Field Coordinator		E-Mail: charles.jensen@encana.com

#### DESCRIPTION OF SPILL OR RELEASE

Date of Incident: 11/16/2013	Facility Name & No.: GGU #30-7-1 (G30)	County: Mesa
Type of Facility (well, tank battery, flow line, pit): well pad		QtrQtr: SWNE Section: 30
Well Name and Number: NA		Township: 8S Range: 91W
API Number: 05-077-09083		Meridian: 6th
Specify volume spilled and recovered (in bbls) for the following materials:		
Oil spilled: NA	Oil recov'd: NA	Water spilled: 5
		Water recov'd: 4.5
		Other spilled: NA
		Other recov'd: NA
Ground Water impacted? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Surface Water impacted? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Contained within berm? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Area and vertical extent of spill: 10'x10'	x 0.10'
Current land use: range land	Weather conditions: snow, cold	
Soil/geology description: 331C—Peeler - Leadville families complex, 40 to 85 percent slopes.		
IF LESS THAN A MILE, report distance IN FEET to nearest.... Surface water: 2840' wetlands: NA buildings: NA		
Livestock: NA water wells: NA Depth to shallowest ground water: >100'		
Cause of spill (e.g., equipment failure, human error, etc.): equipment failure		
Detailed description of the spill/release incident: During well completion work, a crack in a valve developed and produced water leaked onto the ground. The pump was shut in and free liquids were recovered. The part was replaced.		

#### CORRECTIVE ACTION

Describe immediate response (how stopped, contained and recovered):  
The operation was shut down and free liquids were recovered using a vacuum truck.

Describe any emergency pits constructed:  
NA

How was the extent of contamination determined:  
Visual observation.

Further remediation activities proposed (attach separate sheet if needed):  
No further remediation recommended.

Describe measures taken to prevent problem from reoccurring:  
More frequent inspections of the equipment when ambient air temperatures are below freezing.

#### OTHER NOTIFICATIONS

List the parties and agencies notified (County, BLM, EPA, DOT, Local Emergency Planning Coordinator or other).

Date	Agency	Contact	Phone	Response

Spill/Release Tracking No: 2146988

