



STATE OF COLORADO

Andrews - DNR, Doug <doug.andrews@state.co.us>

## COGCC Form 2A review for Foundation Energy Management's Wickstrom 6-4 location - Doc #400477369

2 messages

Andrews - DNR, Doug <doug.andrews@state.co.us>

Thu, Nov 14, 2013 at 10:32 AM

To: sryan@foundationenergy.com

Cc: mstark@foundationenergy.com

Scott,

I have reviewed the referenced Form 2A Oil & Gas Location Assessment and have a few comments.

1) Per COGCC Rule 303.b.(3)C, a description of all oil, gas, and/or water pipelines is required to be included in the Facilities section of the Form 2A. Please provide me with the number, size and material of all pipelines planned for this oil and gas location.

2) During my review, I identified on the USGS Topographic Map and aerial photos an intermittent pond located approximately 2,570 feet northwest and topographically downgradient of the oil and gas location. Therefore, I will change the Water Resources section of the Form 2A to reflect this distance to the nearest surface water feature.

3) Per COGCC Rule 609, groundwater baseline sampling and monitoring and water well sampling applies to all oil and gas wells permitted after May 1, 2013. Although there is a comment on the associated Form 2 APD indicating Foundation Energy will be requesting an exception to this requirement via a Form 4 Sundry Notice, until such time as this exception is granted, Foundation Energy will be required to comply with Rule 609. Therefore, I will change the Water Resources section of the Form 2A to reflect this.

4) While the correct NRCS Soil Map Unit Name was listed in the Soils section of the Form 2A, the required NRCS Soil Map Unit Description attachment was not included with the Form 2A. Please provide me with the NRCS Soil Map Unit Description for the 54 Platner loam, 0-3 percent slopes and I will add it to the Form 2A.

Please respond to these requests by December 14, 2013. If you have any questions, please feel free to contact me. Thank you.

—  
*Doug Andrews*

Oil & Gas Location Assessment Specialist - Northeast Area  
Colorado Oil & Gas Conservation Commission  
1120 Lincoln St., Suite 801  
Denver, CO 80203

[doug.andrews@state.co.us](mailto:doug.andrews@state.co.us)  
303-894-2100 Ext. 5180

Scott Ryan <sryan@foundationenergy.com>

Wed, Nov 20, 2013 at 1:08 PM

To: "Andrews - DNR, Doug" <doug.andrews@state.co.us>

Cc: Matt Stark <mstark@foundationenergy.com>

Doug:

The Wickstrom 6-4 location will have One line of 3 inch welded schedule 80 steel line pipe running northerly parallel to the access road, then easterly to the CTB location.

See attached NRCS Soil Map Unit Description.

Thank you for all the help on this one. I will respond to your comments on the Wickstrom 6 CTB location momentarily. Let me know if you have any questions.

Thanks,

Scott Ryan, RPL

Landman

Foundation Energy Management, LLC

1801 Broadway, Suite 408

Denver, CO 80202

Office: 303-861-0504 x203

Fax: 303-861-0604

Email: [Sryan@foundationenergy.com](mailto:Sryan@foundationenergy.com)



**From:** Andrews - DNR, Doug [mailto:[doug.andrews@state.co.us](mailto:doug.andrews@state.co.us)]

**Sent:** Thursday, November 14, 2013 10:33 AM

**To:** Scott Ryan

**Cc:** Matt Stark

**Subject:** COGCC Form 2A review for Foundation Energy Management's Wickstrom 6-4 location - Doc #400477369

[Quoted text hidden]

---

 **Wickstrom 6-4 Soil Report 54 Platner loam 0-3.pdf**  
33K

