



STATE OF
COLORADO

Allison - DNR, Rick <rick.allison@state.co.us>

Anschutz Windmill 4-22H

Dustin Watt <dwatt@billbarrettcorp.com>

Sat, Oct 19, 2013 at 3:59 PM

To: "Rick Allison (rick.allison@state.co.us)" <rick.allison@state.co.us>, "Roy Rudisill (rrudisill@co.weld.co.us)" <rrudisill@co.weld.co.us>

Cc: Scott Ghan <SGhan@billbarrettcorp.com>, Rusty Frishmuth <rfrishmuth@billbarrettcorp.com>

Rick/Roy,

I just wanted to notify you of a 5bbl oil release from a stuffing box on the Anschutz Windmill 4-22H location. There is perimeter berming and no oil left location. Our midstream partner had high line pressure which caused our well to increase pressure and have a blow out of the stuffing seals.

The well has been shut it and cleanup has begun.

The API # is 05-123-33001, more details to come with the pending form 19.

Thanks,

Dustin Watt

EHS Coordinator

Main: [970-353-0407](tel:970-353-0407) ext. 6005

Mobile: [303-656-1838](tel:303-656-1838)

Fax: [970-353-0691](tel:970-353-0691)

dwatt@billbarrettcorp.com