

FORM
6
Rev
12/05

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
Document Number: 400372952			
Date Received: 02/04/2013			

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.
A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 61250 Contact Name: MARK SHREVE
 Name of Operator: MULL DRILLING COMPANY INC Phone: (316) 264-6366
 Address: 1700 N WATERFRONT PKWY B#1200 Fax: (316) 264-6440
 City: WICHITA State: KS Zip: 67206- Email: MSHREVE@MULLDRILLING.COM

For "Intent" 24 hour notice required, Name: _____ Tel: _____
COGCC contact: Email: _____

API Number 05-061-06871-00 Well Number: 1-24
 Well Name: LARSEN UNIT
 Location: QtrQtr: NWSW Section: 24 Township: 17S Range: 45W Meridian: 6
 County: KIOWA Federal, Indian or State Lease Number: _____
 Field Name: WILDCAT Field Number: 99999

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 38.563400 Longitude: -102.414150
 GPS Data:
 Date of Measurement: 01/22/2013 PDOP Reading: 2.9 GPS Instrument Operator's Name: KEITH WESTFALL
 Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems
 Other _____
 Casing to be pulled: Yes No Estimated Depth: _____
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth

Total: 0 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	318	0	318	0	CALC

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set	40	sks cmt from	4900	ft. to	4800	ft.	Plug Type: OPEN HOLE	Plug Tagged: <input type="checkbox"/>
Set	40	sks cmt from	4000	ft. to	3900	ft.	Plug Type: OPEN HOLE	Plug Tagged: <input type="checkbox"/>
Set	40	sks cmt from	1700	ft. to	1600	ft.	Plug Type: OPEN HOLE	Plug Tagged: <input type="checkbox"/>
Set	40	sks cmt from	1100	ft. to	1000	ft.	Plug Type: OPEN HOLE	Plug Tagged: <input type="checkbox"/>
Set		sks cmt from		ft. to		ft.	Plug Type: _____	Plug Tagged: <input type="checkbox"/>

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)

Set 50 sacks half in. half out surface casing from 368 ft. to 268 ft. Plug Tagged:
 Set 15 sacks at surface
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
 Set 5 sacks in rat hole Set 5 sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: 0 ft. of 8+5/8 inch casing Plugging Date: 01/09/2013
 *Wireline Contractor: _____ *Cementing Contractor: _____
 Type of Cement and Additives Used: _____
 Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: MARK SHREVE
 Title: PRESIDENT Date: 2/4/2013 Email: MSHREVE@MULLDRILLING.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: MOOS, JUSTIN Date: 12/4/2013

CONDITIONS OF APPROVAL, IF ANY:

COA Type	Description

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
400372952	FORM 6 SUBSEQUENT SUBMITTED
400377529	CEMENT JOB SUMMARY
400377530	WELLBORE DIAGRAM

Total Attach: 3 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total: 0 comment(s)