



Fwd: PRE Resources Form 19 spill reports following onsite inspection

1 message

Fischer - DNR, Alex <alex.fischer@state.co.us>

Tue, Feb 4, 2014 at 9:06 AM

To: OGCC EnviroScan - DNR <ogcc.enviroscan@state.co.us>, brollins@olssonassociates.com, Jerry Smothermon <jerrydsmo@msn.com>

Cc: Kris Neidel - DNR <kris.neidel@state.co.us>, Emily Waldron - DNR <emily.waldron@state.co.us>

Amber- Please data enter and upload the three (3) Form 19s to Facility ID: 116589, Location ID: 312756.

Please respond to ALL with the Spill Tracking Numbers. Please upload this email to Facility ID: 116589 and the Form 19s.

Note: Form 19 HU and BV can be closed with a 19A.

Note: Form 19 Drain Line can be closed with a 19A

Form 19 Tank 4 Truck Connection shall remain open.

Jerry and Blair- A site diagram or aerial shall accompany all future spill reports. Additionally, the water well identified approximately 1200 feet north of the Facility is a well that serviced the former Town of Loyd from the 1920s to the 1950s. Current records indicate that this well is still serviceable and flows under artesian conditions. Receipt Number 0300527, Permit Number 11851-AD.

Additionally, the discharge of the pits is into Seeping Spring Gulch with wetlands present as indicated on the Form 19s. One would expect ground water to be present at shallow depths.

A detailed Form 27 shall be prepared and submitted as it relates to the Tank 4 Truck Connection. This Form 27 will not only address the alleged impact near the Tank 4 Truck Connection, but will address the **entire** tank battery. This Form 27 shall address potential subsurface soil impacts as well as potential shallow groundwater impacts. Please refer to the Spill Tracking Number that will be assigned to the Form 19 Tank 4 Truck Connection. The Form 27 shall be submitted to the COGCC by close of business on February 28, 2014.

Thanks

Alex

----- Forwarded message -----

From: **Blair Rollins** <brollins@olssonassociates.com>

Date: Fri, Dec 27, 2013 at 9:28 AM

Subject: PRE Resources Form 19 spill reports following onsite inspection

To: "'Alex.Fischer@state.co.us' (Alex.Fischer@state.co.us)" <Alex.Fischer@state.co.us>

Cc: "Jerry Smothermon (jerrydsmo@msn.com)" <jerrydsmo@msn.com>

Alex,

Attached please find three spill reports as identified during last week's onsite inspection of the PRE Resources tank battery. These spill reports correlate to the following numbered points on the field notes provided:

Field note #3 = Tank 4 truck connection

Field note #27 = Hammer union and ball valve

Field note #30 = 3" drain line pinhole leak

Please let me know if you have any questions or concerns with the provided spill reports.

Thank you for your time,

Blair K. Rollins | Olsson Associates

760 Horizon Drive Ste 102 | Grand Junction, CO 81506 | brollins@olssonassociates.com

TEL [970.263.7800](tel:970.263.7800) | CELL [970.216.6329](tel:970.216.6329) | DIRECT [970.263.6013](tel:970.263.6013)



Alex Fischer, P.G.

Environmental Supervisor, Western Colorado

State of Colorado, Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801

Denver, Colorado 80203

office: [303.894-2100](tel:303.894.2100) ext. 5138 | fax: [303.894-2109](tel:303.894.2109)

email: alex.fischer@state.co.us

3 attachments

 **Form 19 Spill report 12.19.13 Tank 4 truck connection_submittal.pdf**
28K

 **Form 19 Spill report 12.19.13 HU and BV_submittal.pdf**
28K

 **Form 19 Spill report 12.19.13 drain line_submittal.pdf**
28K

