



STATE OF
COLORADO



02122034

RECEIVED

JAN 27 2014

COGCC/Rifle Office

Change of P&A procedure on the Ivory 2-34 (103-09975)

1 message

Krabacher - DNR, Jay <jay.krabacher@state.co.us>

Mon, Jan 27, 2014 at 10:53 AM

To: clark23j@kochind.com

Cc: Emily Waldron - DNR <emily.waldron@state.co.us>, "Keidel, Janni" <Janni.Keidel@kochind.com>

Greetings, John:

We just discussed the ongoing P&A of the subject well. You said that after having set the CICR at 940', you tried to pump (1/3 bbl/minute? if I recall) through the retainer. The plan was to get cement into the perms. The well would pressure up to 600 psi. I agreed with you when you asked about stinging out of the retainer, not trying to pump cement below it, and filling the rest of the casing with cement to the surface. This decision was also facilitated by the CBL showing cement to surface as well.

Regards,

Jay Krabacher

N W Area Engineer

C O G C C

cosas son mas como son ahora que ellas siempre fueron