



February 4, 2014

Mr. Matt Lepore
Colorado Oil & Gas Conservation Commission
1120 Lincoln Street, Suite 801
Denver, CO 80203

Re: Request for Rule 317.o Exception (Open Hole Logging Requirements)

Mumby State 4A-36H P266	SESE Sec 36-T2N-R66W
Mumby State 4B-36H P266	SESE Sec 36-T2N-R66W
Mumby State 4C-36H P266	SESE Sec 36-T2N-R66W
Mumby State 4D-36H P266	SESE Sec 36-T2N-R66W
Mumby State 4E-36H P266	SESE Sec 36-T2N-R66W
Mumby State 4F-36H P266	SESE Sec 36-T2N-R66W
Mumby State 4G-36H P266	SESE Sec 36-T2N-R66W
Mumby State 4H-36H P266	SESE Sec 36-T2N-R66W
Weld County, CO	

Dear Mr. Lepore:

Please let this letter serve as a request for a Rule 317.o Exception for the proposed wells listed above. Rule 317.o requires logging all wells with a minimum of a resistivity log with gamma ray to adequately describe the stratigraphy and open hole logs to adequately verify the setting depth of surface casing and aquifer coverage.

Encana has identified the Mumby State #1 well as being in close enough proximity and as having acceptable logs to adequately describe the stratigraphy of the wellbores of the wells proposed on this multi-well pad.

All these wells will have a cement bond log with gamma ray run from the intermediate casing shoe, or as close as possible, to above surface casing shoe to verify the setting depth of surface casing and aquifer coverage.
satisfy the state's request.

The horizontal portion of all these wells will be logged while drilling with a gamma ray tool.

Encana requests approval of an exception to not run any open-hole logs in the vertical and directional build portion and not run a resistivity log in the horizontal portion of these wells.

Encana will report and submit all logs run on the Form 5 for every well..

Thank you for your assistance in this matter. If you have any questions or comments, please contact me at 720-876-5827.

Sincerely,
ENCANA OIL & GAS (USA) INC.

Erin Lind
Permitting Analyst

Encana Oil & Gas (USA) Inc.
Republic Plaza
370 – 17 Street, Suite 1700
Denver, Colorado
United States 80202
t 303.623.2300
f 303.623.2400
www.encana.com