

FORM
6
Rev
12/05

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
Document Number: 400618302			
Date Received:			

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: <u>10254</u>	Contact Name: <u>RICH LARSON</u>
Name of Operator: <u>RED MESA HOLDINGS/O&G LLC</u>	Phone: <u>(970) 588-3302</u>
Address: <u>5619 DTC PARKWAY - STE 800</u>	Fax: <u>(970) 588-3562</u>
City: <u>GREENWOOD</u> State: <u>CO</u> Zip: <u>80111</u>	Email: <u>RLARSON@REDMESA1.COM</u>
For "Intent" 24 hour notice required, Name: <u>Maclaren, Joe</u> Tel: <u>(970) 382-1680</u>	
COGCC contact: Email: <u>joe.maclaren@state.co.us</u>	

API Number <u>05-067-06133-00</u>	Well Number: <u>F-4</u>
Well Name: <u>FERGUSON NO.1</u>	
Location: QtrQtr: <u>NESE</u> Section: <u>33</u> Township: <u>33N</u> Range: <u>12W</u> Meridian: <u>N</u>	
County: <u>LA PLATA</u> Federal, Indian or State Lease Number: _____	
Field Name: <u>RED MESA</u> Field Number: <u>72890</u>	

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 37.059830 Longitude: -108.146770

GPS Data:
Date of Measurement: 10/09/2008 PDOP Reading: 1.9 GPS Instrument Operator's Name: SAM PETERSEN

Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems
 Other _____

Casing to be pulled: Yes No Estimated Depth: _____

Fish in Hole: Yes No If yes, explain details below

Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below

Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
DAKOTA	3438	3480			3524
Total: 1 zone(s)					

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12	10+3/4	32	49	27	49	0	CALC
1ST	7+7/8	4+1/2	10.5	3,524	60	3,480	3,290	CALC

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 12 sks cmt from 3388 ft. to 3288 ft. Plug Type: CASING Plug Tagged:
 Set 51 sks cmt from 2609 ft. to 2509 ft. Plug Type: CASING Plug Tagged:
 Set 51 sks cmt from 1055 ft. to 955 ft. Plug Type: CASING Plug Tagged:
 Set 51 sks cmt from 485 ft. to 385 ft. Plug Type: CASING Plug Tagged:
 Set 10 sks cmt from 100 ft. to 0 ft. Plug Type: CASING Plug Tagged:

Perforate and squeeze at 3388 ft. with 12 sacks. Leave at least 100 ft. in casing 3388 CICR Depth
 Perforate and squeeze at 2609 ft. with 39 sacks. Leave at least 100 ft. in casing 2559 CICR Depth
 Perforate and squeeze at 1055 ft. with 51 sacks. Leave at least 100 ft. in casing 1005 CICR Depth
(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:
 Set _____ sacks at surface
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
 Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____
 *Wireline Contractor: _____ *Cementing Contractor: _____
 Type of Cement and Additives Used: _____
 Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: MONTY COLLINS
 Title: CONSULTANT Date: _____ Email: PATCH1094@YAHOO.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: _____

Attachment Check List

Att Doc Num	Name
400618344	PROPOSED PLUGGING PROCEDURE
400618346	WELLBORE DIAGRAM
400618347	WELLBORE DIAGRAM

Total Attach: 3 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total: 0 comment(s)