

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

400639067

Date Received:

07/03/2014

Spill report taken by:

ALLISON, RICK

Spill/Release Point ID:

437973

SPILL/RELEASE REPORT (INITIAL /w SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: <u>PDC ENERGY INC</u>	Operator No: <u>69175</u>	Phone Numbers
Address: <u>1775 SHERMAN STREET - STE 3000</u>		Phone: <u>(303) 831-3971</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80203</u>		Mobile: <u>()</u>
Contact Person: <u>Brandon Brun</u>		Email: <u>brandon.brun@pdce.com</u>

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 400639067

Initial Report Date: 07/03/2014 Date of Discovery: 06/16/2014 Spill Type: Historical Release

Spill/Release Point Location:

Location of Spill/Release: QTRQTR NWNE SEC 32 TWP 6N RNG 65W MERIDIAN 6

Latitude: 40.451074 Longitude: -104.686782

Municipality (if within municipal boundaries): _____ County: WELD

Reference Location:

Facility Type: TANK BATTERY Facility/Location ID No 322945
 No Existing Facility or Location ID No.
 Well API No. (Only if the reference facility is well) 05-123-

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? No

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? No

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): <u>0</u>	Estimated Condensate Spill Volume(bbl): <u>Unknown</u>
Estimated Flow Back Fluid Spill Volume(bbl): <u>0</u>	Estimated Produced Water Spill Volume(bbl): <u>0</u>
Estimated Other E&P Waste Spill Volume(bbl): <u>0</u>	Estimated Drilling Fluid Spill Volume(bbl): <u>0</u>

Specify: _____

Land Use:

Current Land Use: CROP LAND Other(Specify): _____

Weather Condition: sunny, 70 degrees

Surface Owner: FEE Other(Specify): _____

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State Residence/Occupied Structure Livestock Public Byway Surface Water Supply Area
 As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

On June 13, 2014, a historic dump line release was discovered during routine maintenance activities at the Johnson Oly 1 (Facility# 322945) tank battery. Well Johnson Oly 1 (API# 05-123-12299) produces to this location. The facility was immediately shut in and excavation of impacted soil commenced below the dump line location. Approximately 540 cubic yards of impacted material were removed and disposed of at the Waste Management Landfill in Ault, Colorado under PDC waste manifests. Groundwater was not encountered during excavation activities. A topographic map of the site is included as Figure 1.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
6/18/2014	Landowner	D&D Commodities	970-353-8052	discussed planned cleanup activities

SPILL/RELEASE DETAIL REPORTS

#1 Supplemental Report Date: 07/03/2014

FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE			<input checked="" type="checkbox"/>
PRODUCED WATER	0	0	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>

specify: _____

Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit

Impacted Media (Check all that apply) Soil Groundwater Surface Water Dry Drainage Feature

Surface Area Impacted: Length of Impact (feet): 42 Width of Impact (feet): 22

Depth of Impact (feet BGS): 18 Depth of Impact (inches BGS): _____

How was extent determined?

Excavation activities commenced on June 16, 2014, following the discovery of a historic release adjacent to the buried dump lines at the Johnson Oly 1 tank battery. Approximately 540 cubic yards of impacted material were removed and transported to the Waste Management Landfill in Ault, Colorado under PDC waste manifests. The vertical and lateral extents of the excavation were determined in the field using a photoionization detector (PID) to measure volatile organic compound (VOC) concentrations in soil. On June 16, 2014, four soil samples (SS01 – SS04) were collected from the base and sidewalls of the excavation area and submitted to Summit Scientific Laboratories in Golden, Colorado for laboratory analysis of benzene, toluene, ethylbenzene, and total xylenes (BTEX), total petroleum hydrocarbons (TPH)-gasoline range organics (GRO), and naphthalene by EPA Method 8260B. Samples were also submitted for analysis of TPH-diesel range organics (DRO) by EPA Method 8015. Analytical results indicated residual hydrocarbon impacts were present on the sidewalls and the base (approximately 18 feet below ground surface [bgs]) of the excavation area.

Soil/Geology Description:

kim loam 1 to 3 percent slopes

Depth to Groundwater (feet BGS) 35

Number Water Wells within 1/2 mile radius: 19

If less than 1 mile, distance in feet to nearest

Water Well	<u>1116</u>	None <input type="checkbox"/>	Surface Water	<u>1965</u>	None <input type="checkbox"/>
Wetlands	_____	None <input checked="" type="checkbox"/>	Springs	_____	None <input checked="" type="checkbox"/>
Livestock	_____	None <input checked="" type="checkbox"/>	Occupied Building	<u>1385</u>	None <input type="checkbox"/>

Additional Spill Details Not Provided Above:

Between June 18 and June 19, 2014, excavation of impacted soil was subsequently conducted. Twelve soil samples (SS05 – SS16) were collected from the sidewalls of the excavation area at depth intervals of 8 feet bgs and 14 feet bgs. Soil samples were submitted for laboratory analysis of BTEX, naphthalene, and TPH – GRO/DRO. Analytical results indicated constituent concentrations in soil samples collected from the sidewalls of the excavation area are below regulatory standards, with the exception of those collected from the northeast sidewall (SS09/SS10). However, impacted soil adjacent to SS09 and SS10 was not removed due to the presence of a buried gas line owned by others. Consequently, four soil samples (TP01 – TP04) were collected from a test pit located northeast of the buried gas line to delineate the lateral extent of the residual hydrocarbon plume. Analytical results indicate constituent concentrations in the test pit location are below regulatory standards. Groundwater was not encountered during excavation activities. Soil analytical results are summarized on Table 1 and the laboratory analytical reports are included as Attachment A. The excavation extent and soil sample locations are illustrated on Figure 2.

CORRECTIVE ACTIONS

#1 Supplemental Report Date: 07/03/2014

Cause of Spill (Check all that apply) Human Error Equipment Failure Historical-Unknown
 Other (specify) _____

Describe Incident & Root Cause (include specific equipment and point of failure)

A dumpline failed which caused a spill to the subsurface

Describe measures taken to prevent the problem(s) from reoccurring:

The dump lines were replaced during battery reconstruction and PDC will continue yearly production line testing once the location is back to being operational.

Volume of Soil Excavated (cubic yards): 540

Disposition of Excavated Soil (attach documentation) Offsite Disposal Onsite Treatment
 Other (specify) _____

Volume of Impacted Ground Water Removed (bbls): 0

Volume of Impacted Surface Water Removed (bbls): 0

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: Corrective Actions Completed (documentation attached)
 Work proceeding under an approved Form 27
 Form 27 Remediation Project No: _____

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Brandon Brun
 Title: EHS Supervisor Date: 07/03/2014 Email: brandon.bruns@pdce.com

COA Type	Description

Attachment Check List

Att Doc Num	Name
400639067	FORM 19 SUBMITTED
400639069	SITE MAP
400639070	ANALYTICAL RESULTS

Total Attach: 3 Files

General Comments

User Group

Comment

Comment Date

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total: 0 comment(s)