

**FORM**  
**6**  
Rev  
12/05

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
Document Number: 400606922			
Date Received: 05/18/2014			

**WELL ABANDONMENT REPORT**

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.  
A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 10044 Contact Name: Jack Sosebee  
 Name of Operator: RED RIVER RANCH HOLDINGS LLC Phone: (303) 921-9176  
 Address: 15850 COUNTY RD 13 Fax: \_\_\_\_\_  
 City: WESTON State: CO Zip: 81091 Email: jack.sosbee@willbros.com

**For "Intent" 24 hour notice required,** Name: DURAN, JOHN Tel: (719) 846-4715  
**COGCC contact:** Email: john.duran@state.co.us

API Number 05-071-08960-00 Well Number: 2-1 R68W  
 Well Name: RRR  
 Location: QtrQtr: NWSW Section: 2 Township: 35S Range: 68W Meridian: 6  
 County: LAS ANIMAS Federal, Indian or State Lease Number: \_\_\_\_\_  
 Field Name: PURGATOIRE RIVER Field Number: 70830

Notice of Intent to Abandon  Subsequent Report of Abandonment

*Only Complete the Following Background Information for Intent to Abandon*

Latitude: 37.024260 Longitude: -104.969980  
 GPS Data:  
 Date of Measurement: 01/31/2007 PDOP Reading: 6.0 GPS Instrument Operator's Name: GARY L TERRY, PLS  
 Reason for Abandonment:  Dry  Production for Sub-economic  Mechanical Problems  
 Other \_\_\_\_\_  
 Casing to be pulled:  Yes  No Estimated Depth: \_\_\_\_\_  
 Fish in Hole:  Yes  No If yes, explain details below  
 Wellbore has Uncemented Casing leaks:  Yes  No If yes, explain details below  
 Details: \_\_\_\_\_

**Current and Previously Abandoned Zones**

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
RATON COAL	627	631			
VERMEJO COAL	1447	1655			
Total: 2 zone(s)					

**Casing History**

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
CONDUCTOR	15	13+3/4	30	24	10	24	0	CALC
SURF	11	8+5/8	32	206	75	206	0	CALC
1ST	7+7/8	5+1/5	15.5	2,005	351	2,004	52	CBL

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 580 with 2 sacks cmt on top. CIBP #2: Depth 256 with 15 sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 15 sks cmt from 256 ft. to 156 ft. Plug Type: CASING Plug Tagged:   
Set 5 sks cmt from 52 ft. to 0 ft. Plug Type: CASING Plug Tagged:   
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged:   
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged:   
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged:

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
(Cast Iron Cement Retainer Depth)

Set \_\_\_\_\_ sacks half in. half out surface casing from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Tagged:

Set 15 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker:  Yes  No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ inch casing Plugging Date: \_\_\_\_\_

\*Wireline Contractor: \_\_\_\_\_ \*Cementing Contractor: \_\_\_\_\_

Type of Cement and Additives Used: \_\_\_\_\_

Flowline/Pipeline has been abandoned per Rule 1103  Yes  No \*ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Jack Sosebee

Title: Consultant Date: 5/18/2014 Email: jack.sosebee@willbros.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: SUTPHIN, DIRK Date: 8/11/2014

**CONDITIONS OF APPROVAL, IF ANY:** \_\_\_\_\_

Expiration Date: 2/10/2015

#### **COA Type**

#### **Description**

	1) Provide 48 hour notice of MIRU via electronic Form 42. 2) Cement from 50' to surface in production casing and surface/production annulus. CBL indicates TOC at 52'.
--	--

## Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
2519265	PROPOSED PLUGGING PROCEDURE
2519266	WELLBORE DIAGRAM
400606922	FORM 6 INTENT SUBMITTED

Total Attach: 3 Files

## General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Engineer	Proposed CIBP at 597' on procedure and WBD is at collar. Moved to 580'. Added existing Rton and Vrmj perms that were missing from form. Form originally had CIBP at 1417' and missing the one at 597'.	8/11/2014 9:46:07 AM
Permit	Attached Raton information and revised form.	3/8/2014 1:29:48 PM
Permit	Requested Raton information again.	7/16/2014 6:57:37 AM
Permit	Form 7's submitted.	7/16/2014 6:51:15 AM
Permit	Missing Raton completion in plugging procedure	5/28/2014 7:14:54 AM
Permit	Missing form 7's after July 2013.	5/28/2014 7:14:49 AM

Total: 6 comment(s)