



State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 881, Denver, Colorado 80203 (303) 894-2100 Fax: (303) 894-2109



FOR OGCC USE ONLY

BRADENHEAD TEST REPORT

Step 1. Record all tubing and casing pressures as found.
Step 2. Sample now, if intermediate or surface casing pressure > 25 psi. In sensitive areas, 1 psi.
Step 3. Conduct Bradenhead test.
Step 4. Conduct intermediate casing test.
Step 5. Send report to BLM within 30 days and to OGCC within 10 days. Include wellbore diagram if not previously submitted or if wellbore configuration has changed since prior program. Attach gas and liquid analyses if sampled.

1. OGCC Operator Number: <u>10084</u>	3. BLM Lease No: <u>N/A</u>	11. Date of Test: <u>10-23-11</u>
2. Name of Operator: <u>Pioneer Resources</u>	5. Multiple completion? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	12. Well Status: <input type="checkbox"/> Flowing <input type="checkbox"/> Shut in
4. API Number: <u>05-071-08544</u>	Number: <u>23-16-82</u>	<input type="checkbox"/> Gas Lift <input checked="" type="checkbox"/> Pumping <input type="checkbox"/> Injection
6. Well Name: <u>State</u>	7. Location (Qtr, Sec, Twp, Rng, Meridian): <u>NE/4 Sec. 16-33S-67W</u>	<input type="checkbox"/> Cyclic/Intermittent
8. County: <u>Las Animas</u>	9. Field Name: <u>Purgatoire River</u>	<input type="checkbox"/> Plunger Lift
10. Minerals: <input type="checkbox"/> Fee <input checked="" type="checkbox"/> State <input type="checkbox"/> Federal <input type="checkbox"/> Indian		13. Number of Casing Strings: <input checked="" type="checkbox"/> Two <input type="checkbox"/> Three <input type="checkbox"/> Liner?

STEP 1: EXISTING PRESSURES					
Record all pressures as found	Tubing: Fm: <u>10</u>	Tubing: Fm: <u>9</u>	Prod. Casing: Fm: <u>9</u>	Intermediate Cag: <u>9</u>	Surface Casing: <u>0</u>

15. STEP 2: See instructions above.

STEP 3: BRADENHEAD TEST						
Buried valve? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Confirmed open? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Elapsed Time (Min Sec)	Fm: Tubing	Fm: Tubing	Production Casing PSIG	Intermediate Casing PSIG
With gauges monitoring production, intermediate casing and tubing pressures, open surface casing (bradenhead) valve (if no intermediate casing, monitor only the production casing and tubing pressures.) Record pressures at five minute intervals. Define characteristics of flow in "Bradenhead Flow" column using letter designations below: O = No Flow; C = Continuous; D = Down to 0; V = Vapor H = Water H2O; M = Mud; W = Whisper; S = Surge; G = Gas		00:	<u>10</u>	<u>9</u>	<u>9</u>	<u>0</u>
BRADENHEAD SAMPLE TAKEN? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Gas <input type="checkbox"/> Liquid		05:				
Character of Bradenhead fluid: <input type="checkbox"/> Clear <input type="checkbox"/> Fresh		10:				
<input type="checkbox"/> Sulfur <input type="checkbox"/> Salty <input type="checkbox"/> Black		15:				
<input type="checkbox"/> Other: (describe)		20:				
Sample cylinder number:		25:				
		30:				
Note instantaneous Bradenhead PSIG at end of test: >						

STEP 4: INTERMEDIATE CASING TEST						
Buried valve? <input type="checkbox"/> Yes <input type="checkbox"/> No	Confirmed open? <input type="checkbox"/> Yes <input type="checkbox"/> No	Elapsed Time (Min Sec)	Fm: Tubing	Fm: Tubing	Production Casing PSIG	Intermediate Casing PSIG
With gauges monitoring production casing and tubing pressures, open the intermediate casing valve. Record pressures at five minute intervals. Characterize flow in "Intermediate Flow" column using letter designations below: O = No Flow; C = Continuous; D = Down to 0; V = Vapor H = Water H2O; M = Mud; W = Whisper; S = Surge; G = Gas		00:				
INTERMEDIATE SAMPLE TAKEN? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Gas <input type="checkbox"/> Liquid		05:				
Character of intermediate fluid: <input type="checkbox"/> Clear <input type="checkbox"/> Fresh		10:				
<input type="checkbox"/> Sulfur <input type="checkbox"/> Salty <input type="checkbox"/> Black		15:				
<input type="checkbox"/> Other: (describe)		20:				
Sample cylinder number:		25:				
		30:				
Note instantaneous Intermediate Casing PSIG at end of test: >						
18. Comments: <u>LIQUID RMS</u>						

19. STEP 5: See instructions above.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Test Performed by: Kevin Modes

Title: Lease Operator

Phone: 714-846-7858

Signed: Kevin Modes

Title:

Date: 10-23-11

WITNESSED BY:

Title:

Agency: