



**BRADENHEAD TEST REPORT**

Step 1. Record all tubing and casing pressures as found.  
 Step 2. Sample now, if intermediate or surface casing pressure >25 psi. In sensitive areas, 1 psi.  
 Step 3. Conduct Bradenhead test.  
 Step 4. Conduct intermediate casing test.  
 Step 5. Send report to BLM within 30 days and to OGCC within 10 days. Include wellbore diagram if not previously submitted or if wellbore configuration has changed since prior program. Attach gas and liquid analyses if sampled.

1. OGCC Operator Number: 10084  
 2. Name of Operator: Pioneer Natural Resources License No: \_\_\_\_\_  
 4. API Number: 25-071-07063 5. Multiple completion?  Yes  No  
 7. Well Name: News Radio Number: 13-13  
 8. Location (Qtr/Sec, Twp, Rng, Meridian): NW/4 sec 13, T34S-R65W  
 9. Field Name: Purgatoire River  
 10. Minerals:  Fee  State  Federal  Indian  
 11. Date of Test: 11/2/2011  
 12. Well Status:  Flowing  Shut In  
 Gas Lift  Pumping  Injection  
 Clock/Intermittent  Plunger Lift  
 13. Number of Casing Strung:  Two  Three  Liner?

14. **STEP 1: EXISTING PRESSURES**

Record all pressures as found	Tubing: Fm: <u>0 PSI</u>	Tubing: Fm: _____	Prod. Casing: Fm: <u>4 PSI</u>	Intermediate Csg: _____	Surface Casing: Fm: <u>8 PSI</u>
-------------------------------	--------------------------	-------------------	--------------------------------	-------------------------	----------------------------------

18. **STEP 2: See instructions above.**

16. **STEP 3: BRADENHEAD TEST**

Buried valve?  Yes  No Confirmed open?  Yes  No

With gauges monitoring production, intermediate casing and tubing pressures, open surface casing (bradenhead) valve (if no intermediate casing, monitor only the production casing and tubing pressures.) Record pressures at five minute intervals. Define characteristics of flow in "Bradenhead Flow" column using letter designations below:  
 O = No Flow; C = Continuous; D = Down to 0; V = Vapor  
 H = Water H2O; M = Mud; W = Whisper; S = Surge; G = Gas

Elapsed Time (Min/Sec)	Fm: _____ Tubing:	Fm: _____ Tubing:	Production Casing PSIG	Intermediate Casing PSIG	Bradenhead Flow:
00:			4		8
05:	?		?		?
10:	?		?		?
15:	?		?		?
20:	?		?		?
25:	?		?		?
30:	?		?		?

BRADENHEAD SAMPLE TAKEN?  Yes  No  Gas  Liquid  
 Character of Bradenhead fluid:  Clear  Fresh  Sulfur  Salty  Black  Other (describe) \_\_\_\_\_  
 Sample cylinder number: \_\_\_\_\_

Note instantaneous Bradenhead PSIG at end of test: >

17. **STEP 4: INTERMEDIATE CASING TEST**

Buried valve?  Yes  No Confirmed open?  Yes  No

With gauges monitoring production casing and tubing pressures, open the intermediate casing valve. Record pressures at five minute intervals. Characterize flow in "Intermediate Flow" column using letter designations below:  
 O = No Flow; C = Continuous; D = Down to 0; V = Vapor  
 H = Water H2O; M = Mud; W = Whisper; S = Surge; G = Gas

Elapsed Time (Min/Sec)	Fm: _____ Tubing:	Fm: _____ Tubing:	Production Casing PSIG	Intermediate Casing PSIG	Intermediate Flow:
00:					7533
05:					8080
10:					8668
15:					
20:					
25:					
30:					

INTERMEDIATE SAMPLE TAKEN?  Yes  No  Gas  Liquid  
 Character of intermediate fluid:  Clear  Fresh  Sulfur  Salty  Black  Other (describe) \_\_\_\_\_  
 Sample cylinder number: \_\_\_\_\_

Note instantaneous Intermediate Casing PSIG at end of test: >

18. Comments: \_\_\_\_\_

19. **STEP 5: See instructions above.**

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.  
 Test Performed by: Shane Griffiths Title: Lease Operator Phone: (719) 846-7898  
 Signed: Shane Griffiths Title: \_\_\_\_\_ Date: 11-2-2011  
 WITNESSED BY: \_\_\_\_\_ Title: \_\_\_\_\_ Agency: \_\_\_\_\_