

STATE OF  
COLORADO

EnviroScan - DNR, OGCC &lt;dnr\_ogcc.enviroscan@state.co.us&gt;

DOC 2141773

## Remediation Project 3437 (Energy O&G) - Bayswater Clark1-25 location (05-123-12992)

1 message

**Allison - DNR, Rick** <rick.allison@state.co.us>

Mon, Sep 29, 2014 at 4:43 PM

To: "Meagan M. Miller" &lt;mmiller@bayswater.us&gt;, "Robert W. Carney" &lt;RCarney@bayswater.us&gt;

Cc: Martha Ramos - DNR &lt;martha.ramos@state.co.us&gt;, "Axelson, John" &lt;john.axelson@state.co.us&gt;, OGCC

EnviroScan - DNR &lt;dnr\_ogcc.enviroscan@state.co.us&gt;

Colorado Oil and Gas Conservation Commission (COGCC) files include an unresolved remediation project associated with the Clark 1-25 location in the northwest quarter of the southeast quarter, Section 25, Township 6 North, Range 66 West in Weld County. COGCC Remediation Project Number 3437 was initiated by Energy Oil and Gas Inc., a former Operator of the Clark 1-25.

Project Number 3437 was initiated by Energy Oil & Gas, Inc. for a release at the production facilities, including the steel above ground storage tank and the buried produced water vessel. The workplan included a proposal to excavate impacted soil from the production areas and to remediate the soil onsite. The workplan was approved with the following conditions:

- Representative soil samples must be collected from any excavated area to confirm successful removal of impacted soils. Each sample shall be analyzed for Total Recoverable Petroleum Hydrocarbons (TRPH)
- The workplan proposes that impacted soils will be remediated onsite. Land treatment must be conducted in accordance with 907.e.(2). Additionally, Rule 907.e.(2) states that land-treated oily waste incorporated in place shall not exceed the allowable concentrations in Table 910-1. Therefore, soil samples must be collected from the landfarmed soil and analyzed accordingly for TRPH to determine remedial success.
- Provide copies of the laboratory results and a site map showing sample locations and the land treatment area.

COGCC records do not include any documentation that the conditionally approved workplan was executed. Therefore, COGCC requests Bayswater Exploration and to conduct an investigation to resolve Remediation Project Number 3437. Please submit a Form 27 Site Investigation and Remediation Workplan within 60 days. The assessment should focus on the area around product tank and water vault.

If you have any questions regarding this request, please contact me at [970-461-2970](tel:970-461-2970).

Rick Allison, P.G.

Environmental Protection Specialist, Northeast Colorado



COLORADO

Oil & Gas Conservation  
Commission

Department of Natural Resources

P [970.461.2970](tel:970.461.2970) | F [970.461.4781](tel:970.461.4781) | C [970.623.0850](tel:970.623.0850)

1120 Lincoln Street, Suite 801, Denver, CO 80203

9/30/2014

State.co.us Executive Branch Mail - Remediation Project 3437 (Energy O&G) - Bayswater Clark1-25 location (05-123-12992)

[rick.allison@state.co.us](mailto:rick.allison@state.co.us) | [www.colorado.gov/cogcc](http://www.colorado.gov/cogcc)

***c: file Remediation Project 3437 - COGCC Correspondence to Bayswater***