



Brock Nelson <bnelson@tasman-geo.com>

State Reportable Release

Hamlin, Phil <Phil.Hamlin@anadarko.com>

Thu, Oct 2, 2014 at 10:40 AM

To: "chris.canfield@state.co.us" <chris.canfield@state.co.us>, Roy Rudisill <rrudisill@co.weld.co.us>, Tom Parko <tparko@co.weld.co.us>

Cc: "Schwarz, Paul" <Paul.Schwarz@anadarko.com>, Bob Cornez <rcornez@tasman-geo.com>, Brock Nelson <bnelson@tasman-geo.com>, James Dawe <jimdawe@tasman-geo.com>, "Dinkel, Mike" <Mike.Dinkel@anadarko.com>, "Schneider, Paul" <Paul.Schneider@anadarko.com>, "Chase, Charles" <Charles.Chase@anadarko.com>, "Rothermel, Margaret [LT Environmental]" <Margaret.Rothermel@anadarko.com>

Good morning everyone, we had a State reportable release due to impacts to groundwater which were discovered while repairing a flow line at the location noted below. Please feel free contact me with any questions or concerns.

UPRR 42 Pan Am X #1

SWNE Sec 31 T3N R66W

05-123-08232

Phillip Hamlin

Senior HSE Representative

Anadarko Petroleum Corp.

Office: [970 515 1161](tel:9705151161)

Cell: [707-478-8029](tel:7074788029)

[Click here for Anadarko's Electronic Mail Disclaimer](#)