

Document Number:
400703874

Date Received:
10/08/2014

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 75027 Contact Name: Wayne Mahon

Name of Operator: ROSEWOOD RESOURCES INC Phone: (970) 630-6834

Address: 2101 CEDAR SPRINGS RD STE 1500 Fax: (970) 848-2245

City: DALLAS State: TX Zip: 75201 Email: wmahon@rosewd.com

For "Intent" 24 hour notice required, Name: Schure, Kym Tel: (970) 520-3832

COGCC contact: Email: kym.schure@state.co.us

API Number 05-125-06672-00 Well Number: 1

Well Name: SPORT

Location: QtrQtr: NWNW Section: 34 Township: 4N Range: 46W Meridian: 6

County: YUMA Federal, Indian or State Lease Number: _____

Field Name: WAVERLY Field Number: 90775

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.276656 Longitude: -102.506128

GPS Data:
Date of Measurement: 10/27/2010 PDOP Reading: 2.1 GPS Instrument Operator's Name: Nate Chesley

Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems
 Other _____

Casing to be pulled: Yes No Estimated Depth: _____

Fish in Hole: Yes No If yes, explain details below

Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below

Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
NIOBRARA	2744	2758			

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	8+3/4	7	17	468	150	468	0	CALC
1ST	6+1/4	4+1/2	10.5	2,863	100	2,863	2,050	CALC

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 2694 with 2 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at 518 ft. with 110 sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:
Set _____ sacks at surface
Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____
*Wireline Contractor: _____ *Cementing Contractor: _____
Type of Cement and Additives Used: _____
Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

Intent to Abandon: Fill 4 1/2" and 7" casing from 518' to surface. Cut off casing 5' below ground level, weld on plate and backfill.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Stacey Owston
Title: Office Manager Date: 10/8/2014 Email: sowston@rosewd.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: SUTPHIN, DIRK Date: 10/16/2014

CONDITIONS OF APPROVAL, IF ANY: _____

Expiration Date: 4/15/2015

COA Type

Description

1) Provide 48 hour notice of MIRU via electronic Form 42.
2) Tag shoe plug 50' above surface casing shoe if cement not circulated to surface as proposed, and cement from 50' to surface (in casing and annulus).

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
400703874	FORM 6 INTENT SUBMITTED
400703886	WELLBORE DIAGRAM
400703887	WELLBORE DIAGRAM

Total Attach: 3 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total: 0 comment(s)