

**McCallum Unit #64
224' FNL, 2550' FWL, Sec. 11, T9N, R79W, 6th P.M.
Jackson County, Colorado
API # 05-057-06049**

P&A Procedure Well Status: INJ SI

1. MIRU, control well, ND WH, NU BOP.
2. Release packer and POOH tbg.
3. MIRU wireline to set CIPB @ 1450'+-.
4. Dump bail 2 sx of cement onto plug.
5. Shot 2 sqz hole at 300', 200' below surface shoe.
6. Establish circulation between 4 1/2" csg and 8 5/8" surface csg.
7. Cement from 300' - Surface, 150 sx (50% excess), or until good returns are seen at surface.
8. SD and mointor cement level in 4 1/2" and 8 5/8" casing.
9. Top off if necessary.
10. Cut casing 4' below surface and weld on plate with weep hole.
11. Plate to contain following info.

Bonanza Creek Energy Company, Inc
McCallum #64
API No. 05-057-06049
NENW 11 9N 79W 6th PM