

STATE OF  
COLORADO

EnviroScan - DNR, OGCC &lt;dnr\_ogcc.envirosan@state.co.us&gt;

**Re: ESC NOV'S**

1 message

**Axelson - DNR, John** <john.axelson@state.co.us>

Tue, Oct 21, 2014 at 11:53 AM

To: Brett Robuck &lt;rpllc@msn.com&gt;

Cc: Mari Deminski &lt;Mari.Deminski@state.co.us&gt;, Jeremy Ferrin - DNR &lt;jeremy.ferrin@state.co.us&gt;, OGCC EnviroScan - DNR &lt;OGCC.EnviroScan@state.co.us&gt;, Carson Robuck &lt;carsonrobuck@yahoo.com&gt;

Brett,

COGCC has assigned the following Remediation Project #s for the Form 27s you submitted on Oct 2nd. The approved/signed copies of the Form 27s are attached for your records.

Wierman 4, API 001-08786, Remediation Project # 8687  
Wierman 5, API 001-08787, Remediation Project # 8688  
Wierman 6, API 001-08788, Remediation Project # 8689  
Sauvage 3, API 001-08803, Remediation Project # 8690

Please note, I did not issue NOAVs or require corrective actions for the N Colo Blvd or Kortum locations. It appears that most of those corrective actions you documented on the Form 27s are related to signs, labels and housekeeping issues that would need to be provided to the inspection group via Form 42. As a result, I have not entered those as remediation projects. You could use the information provided in those two submittals to provide a Form 42 and relate it to the inspection that required those corrective actions.

Also, the inspection and NOAV issued to Energy Search for the Wierman #5 required corrective actions to be performed at the well head and related tank battery. I didn't see any documentation that removal of oily waste and confirmation sampling had been performed at the battery. Please remit this information with the supplemental report that includes the sampling results at the well head.

For each remediation, submit a supplemental report with sample location diagram, summary table of analytical results compared to table 910-1 standards and copy of the laboratory report. Please reference the associated remediation project number on all future correspondence related to these locations. When all corrective actions have been made, you will need to make a formal request to close the remediation project. You can do that with the supplemental report if all work has been completed.

Let me know if you have any questions.  
Thank you,

John E. Axelson, P.G.  
East Environmental Supervisor



P 303.894.2100 x5115 | F 303.894.2109 | C 303-916-0527  
1120 Lincoln Street, Suite 801, Denver, CO 80203  
[john.axelson@state.co.us](mailto:john.axelson@state.co.us) | [www.colorado.gov/cogcc](http://www.colorado.gov/cogcc)

Cc. Remediation Project #s 8687, 8688, 8689, 8690 - Correspondence  
NOAV #s 200407197, 200407198, 200407199, 200407200 - Correspondence

On Thu, Oct 2, 2014 at 11:48 PM, Brett Robuck <rpllc@msn.com> wrote:

John,

Please find form 27, receipts, bills of lading for dirt, diagrams, photos, explanation of work so far completed on:  
Energy Search Companies Wierman, Sauvage, Kortum, North Colo Blvd. & Christansen Leases

LT has been contacted and should be there next to do their work up. Matco Well Servicing is to start pulling Wierman & Sauvage wells for plugging.

I will be in the office tomorrow, but will be going out of the country from Saturday October 4th until October 14th, so if we don't talk tomorrow please contact Carson to discuss what we have done so far and plans with LT.

Thank you

**Brett Robuck**

---

#### 4 attachments



**Energy Search Form 27\_Sauvage 3 Signed.pdf**  
2365K



**Energy Search Form 27\_Wierman #5.pdf**  
2126K



**Energy Search Form 27\_Wierman #6 Signed.pdf**  
1855K



**Energy Search Form 27\_Wierman 4 Signed.pdf**  
2088K