

**Fwd: Berry Petroleum House Log Gulch Facility ID: 436375**

1 message

Fischer - DNR, Alex <alex.fischer@state.co.us>
To: OGCC EnviroScan - DNR <ogcc.enviroscan@state.co.us>

Tue, Oct 28, 2014 at 10:04 AM

Please upload email to Facility ID: 436375 and 423846.

----- Forwarded message -----

From: **Fischer - DNR, Alex** <alex.fischer@state.co.us>
Date: Tue, Oct 28, 2014 at 10:02 AM
Subject: Berry Petroleum House Log Gulch Facility ID: 436375
To: "Burns, Bryan" <BBurns@linnenergy.com>
Cc: Steve Jenkins - DNR <steve.jenkins@state.co.us>, Dave Kubeczko - DNR <dave.kubeczko@state.co.us>, John Noto - DNR <john.noto@state.co.us>

Bryan,

I am wrapping up the House Log Gulch Fm 28 review with minimal comments and review of the Latham I-02, Facility ID 423846.

For the the Fm 28 Review the following is needed:

- Berry estimates \$1.5M for financial assurance. Although the COGCC has a third party contractor reviewing the Form 28 and financial assurance, prior to issuing the Form 28, at least \$1.5 M shall be provided to the COGCC. After the third party review, the financial assurance may be adjusted to reflect estimated costs for decommission, remediation, and reclamation of the House Log Gulch Facility. Please contact Martha Ramos ([303-894-2100 Ext. 5123](tel:303-894-2100)) regarding this process.
- I could not find a Form 2A for the House Log Gulch Oil and Gas Location. Please provide the Location ID and Document Number for the Form 2A.

For the Latham I-02, Pit facility ID 423846 the following is needed:

- How long will it take to construct the House Log Gulch Facility?
- COGCC was under the understanding that the Latham I-02, Facility 423846 was in the process of closure. Please advise.
- The Sundry Form 4 provided a historic time line of the Location (Pad History) including a cursory history of the Pit Facility. Please provide specifics of the Pit Facility including: as-built construction of the Pit Facility, maintenance of the Pit Facility performed, use of the Pit Facility, address any inspections and/or notices of alleged violations (NOAVs) and how these inspections and/or NOAVs were addressed.
- What is a realistic time frame for continued use of the Pit Facility?

Thanks

Alex

--

Alex Fischer, P.G.

Environmental Supervisor, Western Colorado



P [303.894.2100](tel:303.894.2100) x5138 | F [303.894.2109](tel:303.894.2109)

1120 Lincoln Street, Suite 801, Denver, CO 80203

| alex.fischer@state.co.us www.colorado.gov/cogcc

--

Alex Fischer, P.G.

Environmental Supervisor, Western Colorado



P [303.894.2100](tel:303.894.2100) x5138 | F [303.894.2109](tel:303.894.2109)

1120 Lincoln Street, Suite 801, Denver, CO 80203

| alex.fischer@state.co.us www.colorado.gov/cogcc