

Site Photos (05-071-06457) 10/14/2014

Location Sign



Erosion occurring at lower portion of access road



Site Photos (05-071-06457) 10/14/2014

Access road has not been recontoured



Access road near the location



Site Photos (05-071-06457) 10/14/2014

Looking East at the location from the access road



Looking Southeast at the location



Site Photos (05-071-06457) 10/14/2014

Looking North from South side of location



Soil stockpile remains with metal stakes on the Southeast side of location

