



November 12, 2014

Colorado Oil & Gas Conservation Commission
1120 Lincoln Street
Suite 801
Denver, CO 80203

Dear COGCC,

I am submitting this letter to inform you of a mistake I noticed on the Burroughs North NENE Pad #1 (Doc #400655044) and the Burroughs SENE Production Facility Pad #1 (Doc #400654282) Form 2A's. The incorrect mineral owner is listed on both Form 2A's. The third Form 2A that goes with this location of wells, the Burroughs SOUTH SENE Pad #1 (Doc #400705762) is correct and is labeled with the correct mineral owner, Anthony and Viola Burroughs-39701 CR 47 Ault, CO 80610. I have spoken with Mr. Burroughs and promised him I would correct this at once. Please let me know if there is anything additionally you need from me to rectify this. I appreciate your attention to this matter.

Sincerely,

Nick Curran

Regulatory Tech
Integrated Petroleum Services, Inc.
1707 Cole Boulevard, Suite 200
Golden, Colorado 80401

P: 720.420.5745

C: 720.445.1793

F: 720.420.5800

nick.curran@iptenergyservices.com

