



Erosion rills off the slope at the West side of location

photo #2





Erosion rills off the slope at the West side of location

photo #3



Sediment deposit around equipment and on roadway

photo #4





Site Photos (05-071-08143)

11/7/2014

Chain used to measure freeboard installed in pit

photo #5



Guy line markers on South side of location did not have a proper marker

photo #6





**Site Photos (05-071-08143)**

**11/7/2014**

Northeast side of location facing Southwest

photo #7



Sediment trap at the Northeast side of location

photo #8

