

Rodgers Federal - 1

Inspection# 675200865

Sign at entrance of location.



Plugged well marker.



Gravel still present on location.



Subsidence from removal of
lines.



Tank containment still in place.



View of cut slope on NW corner
of location. Location has not
been recountoured.

