



Photo 1. View of cobble placed in erosional channels in southern portion of project area.



Photo 2. View of straw wattle placed below cobble in southern portion of project area.



Photo 3. View of erosional channel on eastern side of access road near well pad entrance. Small amount of cobble may not be sufficient to prevent erosion here.



Photo 4. View of new BMP in eastern portion of project area with cobble in erosional gully and straw wattle placed below.