

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

400771679

Date Received:

01/14/2015

Spill report taken by:

Spencer, Stan

Spill/Release Point ID:

159566

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: <u>WPX ENERGY ROCKY MOUNTAIN LLC</u>	Operator No: <u>96850</u>	Phone Numbers
Address: <u>1001 17TH STREET - SUITE #1200</u>		Phone: <u>(970) 6832295</u>
City: <u>DENVER</u>	State: <u>CO</u>	Mobile: <u>(970) 5890743</u>
Zip: <u>80202</u>		Email: <u>karolina.blaney@wpenergy.com</u>
Contact Person: <u>Karolina Blaney</u>		

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 400766594

Initial Report Date: 01/08/2015 Date of Discovery: 01/07/2015 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR NENW SEC 18 TWP 6S RNG 95W MERIDIAN 6Latitude: 39.530146 Longitude: -108.041520Municipality (if within municipal boundaries): _____ County: GARFIELD

Reference Location:

Facility Type: WELL PAD ☒ Facility/Location ID No 335996☐ No Existing Facility or Location ID No.☐ Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? No

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0Estimated Condensate Spill Volume(bbl): >=5 and <100Estimated Flow Back Fluid Spill Volume(bbl): 0Estimated Produced Water Spill Volume(bbl): 0Estimated Other E&P Waste Spill Volume(bbl): 0Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: _____

Land Use:

Current Land Use: NON-CROP LAND

Other(Specify): _____

Weather Condition: cold, sunnySurface Owner: FEE

Other(Specify): _____

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

A drain valve froze on the back of the condensate tank. Approximately 20 bbls of condensate leaked out of the tank through the compromised valve and into the impervious-plastic-lined SPCC containment. The entire release was contained within containment. No fluids escaped the containment. 100 % of the volume released was recovered by a vac truck.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
1/8/2015	COGCC	Stan Spencer	970-625-2497	Initial Form 19
1/8/2015	County	Kirby Wynn	970-625-5905	Email
1/8/2015	Fire Department	David Blair	970-285-9119	Email
1/7/2015	Land owner		-	Email

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 01/14/2015		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	20	20	<input type="checkbox"/>
PRODUCED WATER	0	0	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? <u>YES</u> Was an Emergency Pit constructed? <u>NO</u>			
<i>Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.</i>			
A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit			
Impacted Media (Check all that apply) <input type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): <u>75</u>		Width of Impact (feet): <u>30</u>	
Depth of Impact (feet BGS): _____		Depth of Impact (inches BGS): _____	
How was extent determined?			
By field measurements and mapping with a Trimble GPS unit.			
Soil/Geology Description:			
Parachute-Rhone loams - Loam to extremely channery loam, if present, or unwaeterhed bedrock (Uinta Fm.)			
Depth to Groundwater (feet BGS) <u>60</u>		Number Water Wells within 1/2 mile radius: <u>0</u>	
If less than 1 mile, distance in feet to nearest		Water Well _____ None <input checked="" type="checkbox"/>	Surface Water <u>790</u> None <input type="checkbox"/>
		Wetlands <u>2560</u> None <input type="checkbox"/>	Springs <u>3180</u> None <input type="checkbox"/>
		Livestock _____ None <input checked="" type="checkbox"/>	Occupied Building <u>1370</u> None <input type="checkbox"/>
Additional Spill Details Not Provided Above:			

A drain valve froze on the back of the condensate tank which allowed condensate to flow into the lined SPCC containment structure. When the release was discovered, production personnel had vac trucks dispatched to the location to pull the remaining fluids from the leaking tank and vacuum off the free liquids in the containment structure. The entire release was contained within the lined SPCC containment structure. No fluids migrated out of the containment. The lined SPCC containment structure performed as it was designed and captured all of the fluids from the release allowing for 100 percent recovery.

CORRECTIVE ACTIONS

#1	Supplemental Report Date:	01/14/2015		
Cause of Spill (Check all that apply)		<input type="checkbox"/> Human Error	<input checked="" type="checkbox"/> Equipment Failure	<input type="checkbox"/> Historical-Unknown
		<input type="checkbox"/> Other (specify)		
Describe Incident & Root Cause (include specific equipment and point of failure)				
A drain valve froze on the back of the condensate tank which allowed condensate to flow into the lined SPCC containment structure.				
Describe measures taken to prevent the problem(s) from reoccurring:				
The compromised valve was replaced.				
Volume of Soil Excavated (cubic yards):				
Disposition of Excavated Soil (attach documentation)		<input type="checkbox"/> Offsite Disposal	<input type="checkbox"/> Onsite Treatment	
		<input type="checkbox"/> Other (specify)		
Volume of Impacted Ground Water Removed (bbls):				
Volume of Impacted Surface Water Removed (bbls):				

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: ☒ Corrective Actions Completed (documentation attached)

☐ Work proceeding under an approved Form 27

Form 27 Remediation Project No: _____

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Karolina Blaney

Title: Environmental Specialist Date: 01/14/2015 Email: karolina.blaney@wpenergy.com

COA Type

Description

--	--

Attachment Check List

Att Doc Num	Name
400771679	FORM 19 SUBMITTED
400771718	AERIAL PHOTOGRAPH

Total Attach: 2 Files

General Comments

User Group	Comment	Comment Date
#Error		

Total: 0 comment(s)