

-----Original Message-----

From: Mary Allison [<mailto:mallison@grayhorse.net>]

Sent: Wednesday, December 10, 2014 9:57 AM

To: Diana.Burn@state.co.us

Subject: Colorado GPS 12/10/2014 10:42

Diana,

Per your request I have attached the Leibert, McAtte & Associates, Inc. Land Surveyors report on our Colorado Properties. It appears when the Plugging Report was filed for the Writebol #2 075-05580 the GPS was inadvertently taken from Writebol #3 05-075-05599.

I have requested Crystal to correct my reports which were filed incorrectly. I apologize for that mistake but the wells have always been injected into the Hoxie and not to a pit.

We are sorry for this confusion and hope this corrects the problem.

Mary

LEIBERT – McATEE & ASSOCIATES, INC.
LAND SURVEYORS

P.O. Box 442 • Sterling, CO 80751

Office: (970) 522-1960 • FAX: (970) 522-6930

NOVEMBER 15, 2007

GPS OPERATOR DARREN VEAL

WRITEBOL #2

LATITUDE: 40.61819N

LONGITUDE: 103.33716W

PDOP: 2.2

SECTION 31, T8N, R53W, LOGAN COUNTY, COLORADO